

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	N	M	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58

CON'T

7 8 0 1

REPORT SOURCE L 6 0 5 0 0 0 2 2 0 7 1 1 2 6 8 0 8 1 2 2 6 8 0 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal operation, following maintenance of Control Rod Drive

0 3 | Scram Pilot Solenoids, operability tests were not immediately performed

0 4 | as required by procedure. The required testing was intended to demon-

0 5 | strate scram pilot valve operability to ultimately ensure the CRD scram

0 6 | insertion times as required by Technical Specifications. No conditions

0 7 | adverse to safety or the environment were involved.

0 8 |

[illegible]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Technicians misunderstood the procedure step intent of how operability
1 1 | testing was to be performed. Upon discovery from supervisory review,
1 2 | operability testing was performed as originally intended. Further action
1 3 | entails a procedure change to more precisely describe the proper testing
1 4 | requirements.

FACILITY STATUS (28) 1 5 E
 % POWER 0 9 2 (29) N/A
 OTHER STATUS (30)
 METHOD OF DISCOVERY B (31) Supervisory Review
 DISCOVERY DESCRIPTION (32)

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z (33) Z (34) N/A

7 8 9 10 11

AMOUNT OF ACTIVITY (35)

N/A

44

LOCATION OF RELEASE (36)

N/A

45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	N/A	(39)

PERSONNEL INJURIES		80	
NUMBER	DESCRIPTION	(41)	
1 8 0 0 0 (40)	N/A		

7		8		9		11		12		80	
1		2		3		4		5		6	
LOSS OF OR DAMAGE TO FACILITY (43)											
TYPE DESCRIPTION											
Z		(43)		N/A							

7 8 9 10 PUBLICITY ISSUED DESCRIPTION 8101060546 NRC USE ONLY

2 0 N (44) N/A 68 69 80

NAME OF PREPARER

P. Harrison

PHONE: (315) 343-2110 Ext. 1212⁰

