

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8511070110 DOC. DATE: 85/11/04 NOTARIZED: NO DOCKET #
 FACIL: 50-410 Nine Mile Point Nuclear Station, Unit 2, Niagara Moh. 05000410
 AUTH. NAME AUTHOR AFFILIATION
 MANGAN, C.V. Niagara Mohawk Power Corp.
 RECIP. NAME RECIPIENT AFFILIATION
 BUTLER, W. Licensing Branch 2

SUBJECT: Forwards "Control Sys Common Sensor Line Failure Analysis
 Evaluation Rept" & "Control Sys Common Power Failures
 Evaluation Rept," to close out SER Confirmatory Items
 24 & 26.


DISTRIBUTION CODE: B001D COPIES RECEIVED: LTR 1 ENCL 5 SIZE: 1 + 181
 TITLE: Licensing Submittal: PSAR/FSAR Amdts & Related Correspondence

NOTES:

RECIPIENT		COPIES		RECIPIENT		COPIES	
ID CODE/NAME		LTTR	ENCL	ID CODE/NAME		LTTR	ENCL
NRR/DL/ADL		1	0	NRR LB2 BC		1	0
NRR LB2 LA		1	0	HAUGHEY, M	01	1	0
INTERNAL: ACRS	41	6	0	ADM/LFMB		1	0
ELD/HDS3		1	0	IE FILE		1	0
IE/DEPER/EPB	36	1	0	IE/DQAVT/QAB21		1	0
NRR ROE, M.L.		1	0	NRR/DE/AEAB		1	0
NRR/DE/CEB	11	1	0	NRR/DE/EHEB		1	0
NRR/DE/eqB	13	2	2	NRR/DE/GB	28	2	2
NRR/DE/MEB	18	1	0	NRR/DE/MTEB	17	1	0
NRR/DE/SAB	24	1	0	NRR/DE/SGEB	25	1	0
NRR/DHFS/HFEB40		1	0	NRR/DHFS/LQB	32	1	0
NRR/DHFS/PSRB		1	0	NRR/DL/SSPB		1	0
NRR/DSI/AEB	26	1	0	NRR/DSI/ASB		1	0
NRR/DSI/CPB	10	1	0	NRR/DSI/CSB	09	1	0
NRR/DSI/ICSB	16	1	0	NRR/DSI/METB	12	1	0
NRR/DSI/PSB	19	1	0	NRR/DSI/RAB	22	1	0
NRR/DSI/RSB	23	1	0	REG FILE	04	1	10
RGN1		3	5	RM/DDAMI/MIB		1	0
EXTERNAL: 24X		1	10	BNL (AMDTs ONLY)		1	0
DMB/DSS (AMDTs)		1	0	LPDR	03	1	10
NRC PDR	02	1	10	NSIC	05	1	10
PNL GRUEL, R		1	0				

Encls
 10: PDR
 LPDR
 Reg File
 NSIC
 24X

TOTAL NUMBER OF COPIES REQUIRED: LTR 52 ENCL 44



November 4, 1985
(NMP2L 0526)

Dr. Walter Butler, Chief
Licensing Branch No. 2
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Dear Dr. Butler:

Re: Nine Mile Point Unit 2
Docket No: 50-410

Enclosed for your use are ten copies of the common sensor and common power supply failure analysis reports. This information is supplied to close out Safety Evaluation Report confirmatory items 24 and 26. Based upon the evaluation no failures were identified which would exceed the consequences of the Final Safety Analysis Report Chapter 15 analysis.

Very truly yours,

C. V. Mangan


C. V. Mangan
Senior Vice President

BB:rla
Enclosures
1065G

xc: R. A. Gramm, NRC Resident Inspector
Project File (2)

8511070110 851104
PDR ADDCK 05000410
E PDR

Boo 1/5
*Ench To: POR
L POR
Reg File
NRC
24X*



LOG NO. L 641SUBJECT: Common Sensor &
Common Power Supply
Failures SER Conf.
Issues 24 & 26NRC CORRESPONDENCE DISTRIBUTION LISTNINE MILE POINT UNIT 2 LETTERS

FROM: A. F. Zallnick, Jr.

TO: DISTRIBUTION

Explanation of Action to be Taken:

Distribution Made:

11-5-85

By:

S. Arquette

DISTRIBUTION:

R. ABBOTT
G. AFFLERBACH
J. ASH
W. BAKER
J. BEBKO
C. BECKHAM
W. BRYANT
J. GALLAGHER
G. GRIFFITH
W. HANSEN
B. HOOTEN
J. KROEHLER, JR.

T. LEMPGES
J. MACKENZIE
C. MANGAN
C. MILLIAN
T. PERKINS
J. PERRY
R. PLANT
D. QUAMME
M. RAY (PSC-2 copies)
C. STUART
C. TERRY
J. THOMAS

D. VANDEPUTTE
J. VOUGHT
K. WARD
J. WHEELOCK
S. WILCZEK, JR.
G. WILSON

CONNER & WETTERHAHN
D. HILL(w/attachments)
PACKET
☐ Attachments transmitted☒ Attachments on file in Unit 2 Licensing Files (too bulky for transmission)☒ Letter Only w/transmittal