

50-335

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO:

Mr. W. G. McDonald

FROM:

Florida Power & Light Company
Miami, Florida
A. D. Schmidt

DATE OF DOCUMENT

5/19/77

DATE RECEIVED

5/23/77

☐ LETTER
☐ ORIGINAL
☐ COPY☐ NOTORIZED
☐ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

DESCRIPTION

ACKNOWLEDGED

PLANT NAME:

St. Lucie Unit No. 1

RJL

DO NOT REMOVE
(1-P)

ENCLOSURE

Consists of copies of the 5/11/77 telephone conference memorandum documenting their notification re reportable occurrence concerning a leak appearing in a fillet weld on line 1"-SI-228 on Safety Injection Header 1A2 in containment.....

(2-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

BRANCH CHIEF:

ZIEMANN

W/3 CYS FOR ACTION

LIC. ASST.:

DIGGS

W/ / CYS

ACRS 16 CYS HOLDING/SENT AS CAT B

INTERNAL DISTRIBUTION

REG FILE

NRC PDR

I & E (2)

MIPC

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

GRIMES

BUTLER

HANAUER

TEDESCO/MACCARY

EISENHUT

BAER

SHAO

VOLLMER/BUNGH

KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

LPDR: Ft. Pierce FLA.

TIC:


NSIC:

CONTROL NUMBER

771450084

A04

50



May 19, 1977


PRN-LI-77-153

Regulatory Docket File

Mr. W. G. McDonald, Director
Office of Management Information and
Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. McDonald:

RE: St. Lucie Unit 1
Docket No. 50-335
Reportable Occurrence



On May 11, 1977, we notified the Region II Office of Inspection and Enforcement of a reportable occurrence at St. Lucie Unit 1. In accordance with Regulatory Guide 10.1, two (2) copies of the telephone conference memorandum documenting our notification of Region II are attached.

Very truly yours,

for J R Beusen
A. D. Schmidt
Vice President
Power Resources

MAS/pm

Attachment

cc: Robert Lowenstein, Esquire

771450084

FLORIDA POWER & LIGHT COMPANY
TELEPHONE CONFERENCE MEMORANDUM

to: R.C. Lewis
From: St. Lucie Plant



INCOMING



OUTGOING

DATE 5/11/77

WITH MR. R.C. Lewis OF THE NRC
WITH MR. K.N. Harris OF THE St. Lucie Plant Manager
COPIES TO: MO Shoppman TIME 2:00 pm
A.D. Schmidt - CO Woody COST _____
J.R. Benner CHARGE _____

SUBJECT Line 1-SI-228 Pressure Boundary Leakage FILE LER-335-77-29

DETAILS OF CONFERENCE:

Mr. Harris notified Mr. Lewis that a leak has appeared in a fillet weld on line 1-SI-228 on Safety Injection Header 1A2 in containment. The unit was placed in a cold shutdown condition as this is considered Pressure Boundary Leakage and is being reported under Reg. Guide 1.16 Section 2.a.3 as prompt reportable. This leak appears to be the same type of problem that occurred in 1975 during Hot Functional testing. F&L Engineering is evaluating the leak and line restraints for this header. The three other SI Headers have the same type of drain line restraints and are also being evaluated.

cc: ADS

JRB

MAS

SIGNATURE

K.N. Harris

FLORIDA POWER & LIGHT COMPANY
TELEPHONE CONFERENCE MEMORANDUM

From: St. Lucie Plant



INCOMING



OUTGOING

DATE 5/11/77

WITH MR. R.C. Lewis OF THE NRC

WITH MR. K.N. Harris OF THE St. Lucie Plant Manager

COPIES TO: MA Shoppman TIME 2:00 p.m.

A.D. Schmidt - CO Worley COST _____

J.L. Benner CHARGE _____

SUBJECT Line 1-SI-228 Pressure Boundary Leakage FILE LER-335-77-29

DETAILS OF CONFERENCE:

Mr. Harris notified Mr. Lewis that a leak has appeared in a fillet weld in line 1-SI-228 on Safety Injection Header 1A2 in containment. The unit was placed in a cold shutdown condition as this is considered Pressure Boundary Leakage and is being reported under Reg. Guide 1.16 Section 2.a.3 as prompt reportable. This leak appears to be the same type of problem that occurred in 1975 during hot functional testing. F&L Engineering is evaluating the leak and line restraints for this header. The three other SI Headers have the same type of drain line restraints and are also being evaluated.

cc ADS

JRB

MAS

SIGNATURE

K.N. Harris

1977 MAY 23 PM 12 22

RECEIVED DOCUMENT
PROCESSING UNIT