

January 20, 1977
L-77-25

Norman C. Moseley, Director
Office of Inspection and Enforcement, Region II
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N. W., Suite 1217
Atlanta, Georgia 30303

Dear Mr. Moseley:

REPORTABLE OCCURRENCE No. 335-B-76-05
ST. LUCIE PLANT UNIT 1
DATE OF OCCURRENCE: December 23, 1976
IMPINGEMENT OF AQUATIC ORGANISMS


The attached Non-Routine Environmental Operating Report is being submitted in accordance with Technical Specification 5.6.2.a.2 to provide 30-day notification of the subject occurrence.

Very truly yours,

Robert E. Uhrig
Vice President

REU/JPF/hlc
Attachment

cc: John G. Davis, Office of Inspection & Enforcement, NRC
Robert Lowenstein, Esq.



FLORIDA POWER & LIGHT COMPANY
ST. LUCIE UNIT NO. 1
REPORTABLE OCCURRENCE NO. 335-B-76-05

Title: IMPINGEMENT OF AQUATIC ORGANISMS

A. Description, Analysis and Evaluation

On December 23, 1976, a special surveillance scheduled for that day was not taken, and therefore was missed. Specification 4.2, Impingement of Aquatic Organisms, requires that intake screens washings be examined for a consecutive twenty-four hour period, twice a week. The first surveillance for that week was done on December 20, but the second one, on December 23, was missed.

December 23, 1976 was observed by Florida Power & Light Company as a holiday, along with December 24. Maintenance personnel were not scheduled to work on the holiday to dump the Basket with the washings. When personnel responsible for the surveillance arrived at the site and found no maintenance personnel, they assumed that the surveillance had been rescheduled for the following week, unaware of what the frequency requirements were. Even though procedures exist that tell personnel how often this surveillance must be met, the surveillance was missed.

The above reasons coupled with some communications breakdowns, caused us to miss a Technical Specification Surveillance. One group failed to schedule the required maintenance personnel, and a second group failed to inform the first group that there were no maintenance personnel at the site. Because of this communication breakdown, the missed surveillance was not recognized until Monday, December 27, 1976.

B. Corrective Action

Personnel involved in this program have been instructed to familiarize themselves with the required procedures to insure that any time a surveillance is not performed as scheduled, that the proper personnel be contacted as per procedure in order to initiate corrective action as soon as possible.

Scheduling mechanisms have been implemented to provide follow-up, as an added insurance in case a similar situation develops, and it can be avoided.

12/28/76

U.S.A.E.C
REGULATORY OPERATIONS
REGION II
ATLANTA, GA.
JAN 25 9 26 AM '77