

VIRGINIA ELECTRIC AND POWER COMPANY  
RICHMOND, VIRGINIA 23261

W. L. STEWART  
VICE PRESIDENT  
NUCLEAR OPERATIONS

December 21, 1984

Mr. Harold R. Denton, Director  
Office of Nuclear Reactor Regulation  
Attn: Mr. Steven A. Varga, Chief  
Operating Reactors Branch No. 1  
Division of Licensing  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Serial No: 057A  
NO/JDH/lms  
Docket Nos. 50-280  
50-281  
License Nos. DPR-32  
DPR-37


Gentlemen:

VIRGINIA ELECTRIC AND POWER COMPANY  
SURRY POWER STATION UNIT NOS. 1 AND 2  
SUPPLEMENTAL INFORMATION ON ICCI SYSTEMS

In response to a recent request by the NRC Surry Project Manager, we have reviewed the information provided in our March 23, 1984, letter (Serial No.-047B) for North Anna pertaining to instrumentation for detecting inadequate core cooling. We find that the technical information regarding the inadequate core cooling systems provided in that letter is applicable to Surry. However, the statements regarding operability, implementation schedules, and additional submittals are not applicable. This latter type of information is contained in our correspondence on ICCI previously submitted on the Surry dockets.

We believe that this information will allow you to complete your Safety Evaluation on this issue for Surry. Please contact us if you have any further questions.

Very truly yours,

  
W. L. Stewart

cc: Mr. J. P. O'Reilly  
Regional Administrator  
Region II

Mr. D. J. Burke  
NRC Resident Inspector  
Surry Power Station

*A002  
1/0*

50-338  
50-339

8412280002 841221  
PDR ADDOCK 05000280  
P PDR