



VIRGINIA POWER

June 6, 1985

Mr. Hugh L. Thompson, Jr., Director  
Office of Nuclear Reactor Regulation  
Attn: Mr. Steven A. Varga, Chief  
Operating Reactors Branch No. 1  
Division of Licensing  
U.S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Serial No. 85-428  
NO/JBL:acm  
Docket Nos. 50-281  
License Nos. DPR-37

Gentlemen:

VIRGINIA POWER  
SURRY POWER STATION UNIT 2  
PRELIMINARY STEAM GENERATOR GIRTH WELD  
REPAIR REPORT

Enclosed is the preliminary report as requested concerning the repair of the Steam Generator Girth Welds for Surry Power Station Unit 2.

The final report will be forwarded at a later date when all data has been analyzed.

If you have any questions, or require further information, please contact us.

Very truly yours,

  
W. L. Stewart

Enclosures

8506110419 850606  
PDR ADOCK 05000281  
P PDR

A001  
.1/39

cc: Mr. D. J. Burke  
NRC Resident Inspector  
Surry Power Station

Dr. J. Nelson Grace  
Regional Administrator  
Region II

Mr. J. Don Neighbors  
NRC Project Manager - Surry  
Operating Reactor Branch No. 1  
Division of Licensing