

July 20, 1978
L-78-243

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N. W., Suite 1217
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII-JPO
50-335
50-250, 50-251

We have reviewed IE Bulletin 78-06 which requested that we determine whether Cutler-Hammer Type M relays with a DC coil are used or planned for use in safety-related systems at our facilities. We have performed surveys at St. Lucie Unit 1 and Turkey Point Units 3 and 4 and have found that the subject relays are not in use or planned for use in safety-related systems.

Based on the survey results, our action in response to IE Bulletin 78-06 is complete.

Very truly yours,

Robert E. Uhrig
Robert E. Uhrig
Vice President

REU/MAS/cpc

cc: Director, Office of Inspection and Enforcement
Robert Lowenstein, Esquire

AD 2
GD