

05/11/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
DISTRIBUTION FOR INCOMING MATERIAL

50-316

REC: KEPPLER J G
NRC

ORG: SHALLER D V
IN & MI PWR

DOCDATE: 05/03/78
DATE RCVD: 05/09/78

DOCTYPE: LETTER NOTARIZED: NO

COPIES RECEIVED

SUBJECT:

LTR 1 ENCL 0

CONFIRMING VERBAL REPT OF REPORTABLE OCCURANCE ON 05/03/78 CONCERNING WHEN
UNIT 2 ENTERED MODE 4, THE CONTAINMENT SPRAY PUMP SWITCHES WERE NOT IN THE
AUTOMATIC STANDBY POSITION... ADVISING FOLLOWUP REPT WILL BE SUBMITTED BY
05/16/78.

PLANT NAME: COOK - UNIT 2

REVIEWER INITIAL: XJM
DISTRIBUTOR INITIAL: *u*

***** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *****

NOTES:

1. SEND 3 COPIES OF ALL MATERIAL TO I&E

INCIDENT REPORTS
(DISTRIBUTION CODE A002)

FOR ACTION: BR CHIEF KNIEL**LTR ONLY(4)

INTERNAL:

REG FILE**LTR ONLY(1)

I & E**LTR ONLY(3)

SCHROEDER/IPPOLITO**LTR ONLY(1)

NOVAK/CHECK**LTR ONLY(1)

KNIGHT**LTR ONLY(1)

HANAUER**LTR ONLY(1)

EISENHUT**LTR ONLY(1)

SHAO**LTR ONLY(1)

KREGER/J. COLLINS**LTR ONLY(1)

K SEYFRIT/IE**LTR ONLY(1)

NRC PDR**LTR ONLY(1)

MIPC**LTR ONLY(3)

HOUSTON**LTR ONLY(1)

EEB**LTR ONLY(1)

BUTLER**LTR ONLY(1)

TEDESCO**LTR ONLY(1)

BAER**LTR ONLY(1)

VOLLMER/BUNCH**LTR ONLY(1)

ROSA**LTR ONLY(1)

EXTERNAL:

LPDR'S

ST. JOSEPH, MI**LTR ONLY(1)

TIC**LTR ONLY(1)

NSIC**LTR ONLY(1)

ACRS CAT B**LTR ONLY(16)

COPIES NOT SUBMITTED PER
REGULATORY GUIDE 10.1

DISTRIBUTION: LTR 45 ENCL 0
SIZE: 1P

CONTROL NBR: 781310021

A0 4 60

***** THE END *****

REGULATORY DOCKET FILE COPY



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

US NRC
DISTRIBUTION SERVICES
BRANCH

1978 MAY 9 PM 12 59

RECEIVED DISTRIBUTION
SERVICES UNIT

May 3, 1978

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-74
Docket No. 50-316

Dear Mr. Keppler:

This is to confirm our verbal report to NRC Region III Inspector,
Mr. K.R. Baker, at 0915 hours on May 3, 1978.

At that time we reported that when Unit #2 entered Mode 4, the
Containment Spray Pump switches were not in the automatic standby
position.

A followup report will be submitted by May 16, 1978, as required by
Technical Specification 6.9.1.8.

Sincerely,

D.V. Shaller
Plant Manager

/bab

cc: J.E. Dolan
R.W. Jurgensen
R.F. Kroeger
R. Kilburn
R.J. Vollen BPI
K.R. Baker RO:III
R.C. Callen MPSC
P.W. Steketee, Esq.
G. Charnoff, Esq.
R. Walsh, Esq.
J.M. Hennigan
G. Olson
PNSRC
J.F. Stietzel
Dir., IE (40 copies)
Dir., MTPC (4 copies)

781310021

A002
5/10