

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 12590

FILE: INCIDENT REPORT FILE

FROM: Indiana & Michinga Power Bridgman, Michigan R.W. Jurgensen		DATE OF DOC 10-29-75	DATE REC'D 11-3-75	LTR XXX	TWX	RPT	OTHER
TO: Mr. J. Keppler		ORIG 1	CC 2 Signed	OTHER SENT AEC PDR XXX SENT LOCAL PDR XXX			
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 3	DOCKET NO: 50-315		

DESCRIPTION:

Letter trans the following.....

ENCLOSURES:

Abnormal Occurrence # 75-70, on 10-7-75,
Concerning unoperable Containment Hydrogen
Monitoring System Calibration.....

(3 Copies Received)

PLANT NAME: Cook # 1

FOR ACTION/INFORMATION

SAB 11-7-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	REID W/ Copies

**ACKNOWLEDGED
DO NOT REMOVE**

INTERNAL DISTRIBUTION

REG FILE NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE LEE (L) BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (3) MPC/PE (3) STEELE	TECH REVIEW SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	DENTON **GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	LIC ASST R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	A/T IND. BRAITMAN SALTZMAN MELTZ PLANS MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
--	--	--	---	--

EXTERNAL DISTRIBUTION

1 - LOCAL PDR St. Joseph, Michigan	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
5 - ACRS SENT TO LIC ASST M. Service		
** SEND ONLY TEN DAY REPORTS		

...

...

...

...

...

...


...



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

October 29, 1975



Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:


Pursuant to the requirements of Appendix A Technical Specifications
and the United States Nuclear Regulatory Commission Regulatory Guide
1.16, Revision 3, Section 2.b, the following Abnormal Occurrence
Report is submitted:

AO-50-315/75-70

Regulatory


File Cy.

Sincerely,


R.W. Jurgensen
Plant Manager

/bab

cc: R.S. Hunter
J.E. Dolan
G.E. Lien
R.J. Vollen BPI
R. Kilburn
R.C. Callen MPSC
K.R. Baker RO: III
P.W. Steketee, Esq.
R. Walsh, Esq.
G. Charnoff, Esq.
G. Olson
PNSRC
R.S. Keith
Director, IE (30 copies)
Director, MIPC (3 copies)



12590

LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME					LICENSE NUMBER										LICENSE TYPE					EVENT TYPE					
01	M	I	D	C	C	1	0	0	-	0	0	0	0	0	0	-	0	0	4	1	1	1	1	0	1
7	8	9				14	15											25	26					31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE					REPORT DATE									
01	CON'T	P	O	L	0	5	0	-	0	3	1	5	1	0	0	7	7	5	1	0	2	2	7	5
7	8	57	58	59	60	61							68	69					74	75				80

EVENT DESCRIPTION

02 WHILE IN MODE 1, AT 80 PERCENT POWER, INTERNAL AUDITING
7 8 9 80

03 REVEALED THAT THE CONTAINMENT HYDROGEN MONITORING SYSTEM
7 8 9 80

04 CALIBRATION WAS NOT PERFORMED APRIL 26, 1975 AS REQUIRED
7 8 9 80

05 BY TECHNICAL SPECIFICATIONS PARAGRAPH 4.6.4.1 (A0-50.315/75-70)
7 8 9 80

06
7 8 9 80

7 8 9 SYSTEM CODE CAUSE CODE COMPONENT CODE PRIME COMPONENT SUPPLIER COMPONENT MANUFACTURER VIOLATION

07 ZZ A ZZZZZZ Z ZZZZZZ Y

7 8 9 10 11 12 17 43 44 47 48

CAUSE DESCRIPTION

08 CALIBRATION WAS NOT PERFORMED DUE TO MANPOWER SHORTAGE
7 8 9 80
09 AND WAS NOT RESCHEDULED DUE TO OVERSIGHT. THE SCHEDULE HAS
7 8 9 80
10 BEEN REVISED TO REQUIRE INDIVIDUAL SIGN-OFFS (SEE SUPPLEMENT)
7 8 9 80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	E	08	0	NA		C		INTERNAL AUDITING	
7	8	9	10	12	13	44	45	46	80

FORM OF ACTIVITY RELEASED: 12

CONTENT OF RELEASE: Z

AMOUNT OF ACTIVITY: NA

LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
13	000		Z	NA

PERSONNEL INJURIES

NUMBER				DESCRIPTION
14	0	0	0	NA

OFFSITE CONSEQUENCES

15	NONE
7 8 9	80

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION
16	Z	NA

PUBLICITY

17	NA
----	----

8 ADDITIONAL FACTORS

18 LNA

19 | NA

NAME: G. SWAN.

PHONE: 165-5901(368)

AO-50-315/75 - 79

Supplement to CAUSE DESCRIPTION

when surveillance has been completed and the rescheduling process for missed surveillance has been formalized. No further problems of this type are expected.