

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 12638
FILE: INCIDENT REPORT FILE

FROM: Indiana & Michigan Pwr Co. Bridgman, Michigan R.W. Jurgensen			DATE OF DOC 10-29-75	DATE REC'D 11-3-75	LTR XXX	TWX	RPT	OTHER
TO: J.G. Keppler			ORIG NONE	CC 40	OTHER	SENT AEC PDR _____ SENT LOCAL PDR _____		
CLASS	UNCLASS XXXXX	PROP INFO	INPUT	NO CYS REC'D 40		DOCKET NO: 50-315		

DESCRIPTION:

Ltr. trans the following.....

ENCLOSURES:

Abnormal Occurrence #. 75-70, on 10-7-75, concerning containment Hydrogen Monitoring System Calibration was not performed 4-26-75,

**ACKNOWLEDGED
DO NOT REMOVE**

(40 cys. Rec'd)

PLANT NAME: Cook 1 & 2

FOR ACTION/INFORMATION

VCR 11-4-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	

INTERNAL DISTRIBUTION

REG FILE NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (3) MIPC/PE (3) STEELE	TECH REVIEW SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	DENTON **GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	LIC ASST R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	A/T IND. BRAITMAN SALTZMAN MELTZ PLANS MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
---	--	--	---	--

EXTERNAL DISTRIBUTION

1 - LOCAL PDR <i>St. Joseph Mich</i>	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
1 - ACRS SENT TO LIC ASST		
** SEND ONLY TEN DAY REPORTS		

17-10-19

17-10-19

17-10-19
17-10-19
17-10-19
17-10-19
17-10-19

17-10-19

17-10-19
17-10-19
17-10-19
17-10-19
17-10-19

17-10-19

17-10-19
17-10-19

17-10-19



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106


October 29, 1975



Regulatory Docket File

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License
Docket No. 50-315



Dear Mr. Keppler:

Pursuant to the requirements of Appendix A Technical Specifications
and the United States Nuclear Regulatory Commission Regulatory Guide
1.16, Revision 3, Section 2.b, the following Abnormal Occurrence
Report is submitted:

A0-50-315/75-70

Sincerely,

R.W. Jurgensen
Plant Manager

/bab

cc: R.S. Hunter
J.E. Dolan
G.E. Lien
R.J. Vollen BPI
R. Kilburn
R.C. Callen MPSC
K.R. Baker RO: III
P.W. Steketee, Esq.
R. Walsh, Esq.
G. Charnoff, Esq.
G. Olson
PNSRC
R.S. Keith
Director, IE (30 copies)
Director, MIPC (3 copies)

12638

08081

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

<p>LICENSEE NAME 01 MIDICILL</p>	<p>LICENSE NUMBER 00-00000-00</p>	<p>LICENSE TYPE 411111</p>	<p>EVENT TYPE 01</p>
--	---	--	--

<p>01 CON'T</p>	<p>CATEGORY P0</p>	<p>REPORT TYPE L</p>	<p>REPORT SOURCE L</p>	<p>DOCKET NUMBER 050-0315</p>	<p>EVENT DATE 100775</p>	<p>REPORT DATE 102275</p>
---	--	--	--	---	--	---

EVENT DESCRIPTION

02	WHILE IN MODE 1 AT 80 PERCENT POWER, INTERNAL AUDITING	80
03	REVEALED THAT THE CONTAINMENT HYDROGEN MONITORING SYSTEM	80
04	CALIBRATION WAS NOT PERFORMED APRIL 26, 1975 AS REQUIRED	80
05	BY TECHNICAL SPECIFICATIONS PARAGRAPH 4.6.4.1 (A0-50-315/75-70)	80
06		80

<p>SYSTEM CODE 07 ZZ</p>	<p>CAUSE CODE A</p>	<p>COMPONENT CODE ZZZZZZ</p>	<p>PRIME COMPONENT SUPPLIER Z</p>	<p>COMPONENT MANUFACTURER ZZZZZ</p>	<p>VIOLATION Y</p>
--	---	--	---	---	--

CAUSE DESCRIPTION

08	CALIBRATION WAS NOT PERFORMED DUE TO MANPOWER SHORTAGE	80
09	AND WAS NOT RESCHEDULED DUE TO OVERSIGHT. THE SCHEDULE HAS	80
10	BEEN REVISED TO REQUIRE INDIVIDUAL SIGN-OFFS (SEE SUPPLEMENT)	80

<p>FACILITY STATUS 11 E</p>	<p>% POWER 080</p>	<p>OTHER STATUS NA</p>	<p>METHOD OF DISCOVERY IC</p>	<p>DISCOVERY DESCRIPTION INTERNAUDING</p>
---	--	--	---	---

<p>FORM OF ACTIVITY RELEASED 12 Z</p>	<p>CONTENT OF RELEASE Z</p>	<p>AMOUNT OF ACTIVITY NA</p>	<p>LOCATION OF RELEASE NA</p>
---	---	--	---

PERSONNEL EXPOSURES

<p>NUMBER 13 000</p>	<p>TYPE Z</p>	<p>DESCRIPTION NA</p>
--	---	---

PERSONNEL INJURIES

<p>NUMBER 14 000</p>	<p>DESCRIPTION NA</p>
--	---

OFFSITE CONSEQUENCES

15	NONE	80
--	------	----

LOSS OR DAMAGE TO FACILITY

<p>TYPE 16 Z</p>	<p>DESCRIPTION NA</p>	80
--	---	----

PUBLICITY

17	NA	80
--	----	----

ADDITIONAL FACTORS

18	NA	80
--	----	----

19	NA	80
--	----	----

NAME: G. SWAN

PHONE: 465-5901(368)



2-1
1-1

AO-50-315/75 - 79

Supplement to CAUSE DESCRIPTION

when surveillance has been completed and the rescheduling process for missed surveillance has been formalized. No further problems of this type are expected.



7-1-10

4-1-10

1000