

ROUTING AND TRANSMITTAL SLIP		ACTION
¹ TO (Name, office symbol or location) IE Chief, FSOB IE Chief, FC&EB IE:HQ(4)	INITIALS	CIRCULATE
	DATE	COORDINATION
² Licensing(4) <u>DR Central Files</u> J. Rizzo, OMIPC C. Poslusny, PSB	INITIALS	FILE
	DATE	INFORMATION
³ Region I Region II PDR Local PDR	INITIALS	NOTE AND RETURN
	DATE	PER CON - VERSATION
⁴ NSIC TIC OGC, Beth, P-506A R. Callen	INITIALS	SEE ME
	DATE	SIGNATURE
REMARKS K. Vollen AMERICAN ELECTRIC POWER SERVICE CORPORATION INDIANA AND MICHIGAN POWER COMPANY D. C. COOK PLANT - UNITS 1 AND 2 DOCKET NOS. <u>50-315</u> AND 50-316 Attached is a copy of licensee's reply dated April 26, 1976, to IE Bulletin 76-05.		
Do NOT use this form as a RECORD of approvals, concurrences, disapprovals, clearances, and similar actions		
FROM (Name, office symbol or location) G. Fiorelli, IE:III	DATE	04/30/76
	PHONE	

OPTIONAL FORM 41
 AUGUST 1967
 GSA FPMR (41CFR) 100-11.206

648-16-81594-1 552-103 GPO 5041-101

AMERICAN ELECTRIC POWER Service Corporation



2 Broadway, New York, N. Y. 10004
(212) 422-4800

JOHN E. DOLAN
Senior Executive Vice President
Engineering & Construction

April 26, 1976

Donald C. Cook Nuclear Plant
Docket No. 50-315 and 50-316
DPR No. 58 and CPPR No. 61

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137


Attention: Mr. J. G. Keppler, Regional Director

Gentlemen:

This letter provides the information required by IE Bulletin No. 76-05 entitled "Relay Failures - Westinghouse BFD Relays."

We have received the Westinghouse service letter mentioned in the Bulletin. The relays involved are not in use and are not planned for use in Unit 1 or Unit 2 of the Donald C. Cook Nuclear Plant.

Very truly yours,


John E. Dolan

JED:mam

cc: Dr. E. Volgenau, Director I&E U.S.N.R.C.
G. Charnoff
R. C. Callen
P. W. Steketee
R. Walsh
R. J. Vollen
R. W. Jurgensen - Bridgman
R. S. Hunter

Our Nation's 200th Year **1976** Our Company's 70th Year

413 2 2 1976

