

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

TO: Mr. J. G. Keppler

FROM: Indiana & Michigan Power Company
Bridgman, Michigan
R. W. JurgensenDATE OF DOCUMENT
3/11/77DATE RECEIVED
3/16/77☒ LETTER
☐ ORIGINAL
☐ COPY
☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

One *ce*

DESCRIPTION

ENCLOSURE

Ltr. re rpt. concerning damaged hydraulic snubbers to the Steam Generator Feedwater Lines and a crack in the four inch Auxiliary Feedwater Line to No. 2 Steam Generator.....

ACKNOWLEDGED

(1-P)

PLANT NAME:

Cook Unit No. 1

RJL

DO NOT REMOVE

SAFETY

FOR ACTION/INFORMATION

ENVIRO

ASSIGNED AD:

BRANCH CHIEF:

PROJECT MANAGER:

LIC. ASST.:

ASSIGNED AD:

BRANCH CHIEF:

PROJECT MANAGER:

LIC. ASST.:

INTERNAL DISTRIBUTION

REG FILE

NRC PDR

I & E (2)

OELD

GOSSICK & STAFF

MIPC

CASE

HANAUER

HARLESS

SYSTEMS SAFETY

HEINEMAN

SCHROEDER

ENGINEERING

MACARRY

BOSNAK

SINWEIL

PAWLICKI

PLANT SYSTEMS

TEDESCO

BENAROYA

LAINAS

IPPOLITO

KIRKWOOD

OPERATING REACTORS

STELLO

SITE SAFETY &

ENVIRO ANALYSIS

DENTON & MULLER

ENVIRO TECH.

ERNST

BAILLARD

YOUNGBLOOD

SITE TECH.

GAMMILL

STAPP

HULMAN

SITE ANALYSIS

VOLLMER

BUNCH

J. COLLINS

KREGER

PROJECT MANAGEMENT

BOYD

P. COLLINS

HOUSTON

PETERSON

MELTZ

HELTAMES

SKOVHOLT

REACTOR SAFETY

ROSS

NOVAK

ROSZTOCZY

CHECK

AT & I

SALTZMAN

RUTBERG

OPERATING TECH.

EISENHUT

SHAO

BAER

BUTLER

GRIMES

EXTERNAL DISTRIBUTION

CONTROL NUMBER

LPDR: St Joseph, MI

TIC:

NSIC:

ASLB:

ACRS CYS HOLDING/SENT

NAT. LAB:

REG V. IE

LA PDR

CONSULTANTS:

BROOKHAVEN NAT. LAB.

ULRIKSON (ORNL)

77060370

315
NA4
60

.....

.....

.....

.....


.....



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

March 11, 1977



Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

REGULATORY *DOCKETED 11 MAR 1977*

Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

This is to confirm our verbal report to NRC RO: III Inspector,
Mr. T.L. Harpster and telephone report to NRC RO: III Inspector,
Mr. K.R. Baker at 1630 hours on March 10, 1977.

At that time we reported that the Donald C. Cook Nuclear Plant had
experienced damaged hydraulic snubbers on the Steam Generator
Feedwater Lines and a crack in the four inch Auxiliary Feedwater
Line to No. 2 Steam Generator. Both events occurred after a reactor
trip at approximately 1222 hours.

A followup report will be submitted by March 24, 1977, as required
by Regulatory Guide 1.16, Revision 4, Section 2.a.

Sincerely,

R.W. Jurgensen
Plant Manager

/bab

cc: R.S. Hunter
J.E. Dolan
G.E. Lien
R. Kilburn
R.J. Vollen BPI
K.R. Baker RO: III
P.W. Steketee, Esq.
R. Walsh, Esq.
G. Olson
PNSRC
R.S. Keith

R.C. Callen
G. Charnoff, Esq.
J.M. Hennigan
Dir., IE (40 copies)
Dir., MIPC (4 copies)

770760370

RECEIVED DOCUMENT
PROCESSING UNIT

1977 MAR 16 PM 3 50