

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO: N.C. Moseley

FROM: Tennessee Valley Authority
Chattanooga, TN.
H.S. FoxDATE OF DOCUMENT
7-2-76DATE RECEIVED
7-8-76☒ LETTER
☒ ORIGINAL
☐ COPY☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

40

DESCRIPTION

Ltr. trans the following.....

ENCLOSURE

Licensee Event Rport (R.O. # 765) on 6-19-76
Concerning to HCU that was found incapable of
being scrambled.....

(40 Unsigned Cys. Received)

(2 Pages)

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: Browns Ferry # 1

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED.
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY

FOR ACTION/INFORMATION

ENVIRO

SAB 7-9-76

BRANCH CHIEF: Schwencer

W/3 CYS FOR ACTION

LIC. ASST: Sheppard

W/ -CYS

ACRS 16 CYS. HOLDING/SENT TO LA

INTERNAL DISTRIBUTION

☒ REG FILE

NRC PDR

I & E (2)

MIPC (3)

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

GRIMES/

CASE

Butler

HANAUER

TEDESCO/MACCARY

EISENHUT

BAER

SHAO

VOLLMER/BUNCH

KREGER/J. COLLINS

~~Denise~~

EXTERNAL DISTRIBUTION

CONTROL NUMBER

LPDR: Athens, AL.

TIC

NSIC

6846




382



TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37401

July 2, 1976

Mr. Norman C. Moseley, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
230 Peachtree Street, NW., 8th Floor
Atlanta, Georgia 30303



Dear Mr. Moseley:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 -
DOCKET NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE
OCCURRENCE REPORT BFRO-50-260/765

The enclosed report is to provide details concerning HCU 30-31 that was found incapable of being scrambled due to valves 2-85-612 and 2-85-615 being in the closed position and is submitted in accordance with Appendix E to Regulatory Guide 1.16, Revision 4, August 1975. This event occurred on Browns Ferry Nuclear Plant unit 2.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. S. Fox
Director of Power Production

Enclosure (3)

CC (Enclosure):

Director (3)

Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director (40)

Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

6846



11

11

WISSENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE						
01	R	L	B	R	F	2	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	1							
7	8	9				14	15									25	26					30	31	32							
CATEGORY										REPORT TYPE		REPORT SOURCE		DOCKET NUMBER					EVENT DATE					REPORT DATE							
01	CON'T		*				T		L		0	5	0	-	0	2	6	0	0	6	1	9	7	6							
7	8						57	58	59	60	61							68	69						74	75					80

EVENT DESCRIPTION

02	HCU 30-31 was found incapable of being scrambled due to valves 2-85-612 and	80
03	2-85-615 being in the closed position. Interim Technical Specification 4.3.C	80
04	requires valves 2-85-612 and 2-85-615 for each HCU to be open at all times.	80
05	(BFRO-50-260/765)	80
06		80
	PRIME	80

CAUSE DESCRIPTION

08	Incorrect verification of required valve position caused by personnel	80
09	error.	80
10		80

11	7	8	9	FACILITY STATUS	10	11	12	% POWER	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
11	7	8	9	H	10	11	12	000	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
12	7	8	9	Z	10	11	12	Z	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
12	7	8	9	Z	10	11	12	Z	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
13	000	Z	NA	

PERSONNEL INJURIES

NUMBER			DESCRIPTION
14	000		NA

OFFSITE CONSEQUENCES

[illegible]

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
15	Z		NA

PUBLICITY

17	NA	
7	8	9
		80

ADDITIONAL FACTORS

18	NA	
7	8	9
		80

19 _____ 80

NAME: _____ PHONE: _____

GPO 861-667