




**Consumers  
Power  
Company**

*ASB*

*slb*

General Offices: 212 West Michigan Avenue, Jackson, Michigan 49201 • (517) 788-0550

January 26, 1981



Mr James G Keppler  
Office of Inspection and Enforcement  
Region III  
U S Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60127

DOCKET 50-255 - DPR-20 - PALISADES PLANT -  
LICENSEE EVENT REPORT 81-002 - INADEQUATE  
MOUNTING OF DC DISTRIBUTION PANEL

On the reverse side is LER 81-002 which is reportable under Technical Specifications 6.9.2.B(2).

*David P. Hoffman*

David P Hoffman  
Nuclear Licensing Administrator

CC Director, Office of Nuclear Reactor Regulation  
Director, Office of Inspection and Enforcement  
NRC Resident Inspector, Palisades Plant

*A002  
5/11*

JAN 28 1981

## LICENSEE EVENT REPORT

CONTROL BLOCK:                      (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	M	I	P	A	L	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5																	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33																	
LICENSEE CODE														LICENSE NUMBER										LICENSE TYPE										CAT 58									

CON'T

01	R	L	6	0	5	0	0	0	2	5	5	7	0	1	0	8	8	1	8	0	1	2	6	8	1	9																	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33																	
REPORT SOURCE														DOCKET NUMBER										EVENT DATE										REPORT DATE									

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During post installation review of fire protection modifications, it was  
03 determined that 125 volt DC distribution panel D21A was not adequately  
04 mounted in terms of meeting seismic restraint criteria. The redundant panel  
05 D-11A was properly mounted. The loads supplied by the panel (1-2 Diesel  
06 Gen. and 2400V Bus 1D) were declared inoperable; repairs were initiated &  
07 completed within time required by LCO of TS 3.7.2c. No threat to public  
08 health or safety existed.

09	E	C	11	B	12	A	13	S	U	P	O	R	T	14	X	15	Z	16	17	8	1	0	0	2	0	3	L	0																																																																	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35																																																																	
SYSTEM CODE														CAUSE CODE										COMP. SUBCODE										VALVE SUBCODE																																																											
EVENT YEAR														SEQUENCE REPORT NO.										OCCURRENCE CODE										REPORT TYPE										REVISION NO.																																																	
ACTION TAKEN														EFFECT ON PLANT										SHUTDOWN METHOD										HOURS										ATTACHMENT SUBMITTED										NPRD-4 FORM SUB.										PRIME COMP. SUPPLIER										COMPONENT MANUFACTURER																			
B														Z										Z										00000										N										N										A										N355																			
18														19										20										21										22										23										24										25										26									

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The seismically qualified panel was mounted on a field fabricated frame  
11 which was insufficiently braced. The apparent cause was incorrect  
12 engineering judgement by A/E during project design. To satisfy seismic  
13 restraint criteria, frame was modified by addition of braces.

14	F	28	0	9	8	29	NA	30	D	31	Notification by AE	32	15	Z	33	Z	34	NA	35	NA	36	16	0	0	0	37	Z	38	NA	39	17	0	0	0	40	NA	41	18	Z	42	NA	43	19	N	44	NA	45	20	N	46	NA	47	21		22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47																																																																																																																																																																																																																																																													
FACILITY STATUS														% POWER										OTHER STATUS										METHOD OF DISCOVERY										DISCOVERY DESCRIPTION																																																																																																																																																																																																																																																																																																	
ACTIVITY CONTENT														AMOUNT OF ACTIVITY										LOCATION OF RELEASE										PERSONNEL EXPOSURES										PERSONNEL INJURIES										LOSS OF OR DAMAGE TO FACILITY										PUBICITY																																																																																																																																																																																																																																																																													
RELEASED														DESCRIPTION										NUMBER										TYPE										DESCRIPTION										TYPE										DESCRIPTION										ISSUED										DESCRIPTION																																																																																																																																																																																																																																																									
15														16										17										18										19										20										21										22										23										24										25										26										27										28										29										30										31										32										33										34										35										36										37										38										39										40										41										42										43										44										45										46										47									

NRC USE ONLY