

PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

PHILADELPHIA, PA. 19101

(215) 841-4000

50-277

50-278



October 16, 1975

Division of Reactor Licensing
Office of Nuclear Reactor Regulations
United States Nuclear Regulatory Commission
Washington, D.C. 20555

Regulatory

File Cy.

Attention: Mr. Gordon Dicker

Gentlemen:

Pursuant to the requirement set forth in Section 6.4 of Appendix B of the Technical Specifications for Peach Bottom Units 2 and 3, we are sending you 20 copies of the environmental radiological monitoring program report entitled "Peach Bottom Atomic Power Station - Fulton Generating Station, Radiological Regional Environmental Monitoring Program Report #9, January 1, 1974 through December 31, 1974, by Radiation Management Corporation."


Also enclosed are 20 copies of revised pages for insertion in the Radiation Management Corporation, 1974 Semi-Annual Report sent to you previously. Most of the changes reflected in these resulted from re-analysis of Sr-89 and Sr-90 in soil performed because radium separation may not have been complete in the original analysis. The table of I-131 concentrations in milk samples has been corrected to show all MDLs at the time of sampling rather than at the time of analysis. The remainder of the pages correct typographical and printing errors which were inadvertently included in the Semi-Annual Report.

Very truly yours,

W. B. Willsey
Superintendent
Services Division

WBW:1pm

Attachments (2 boxes)



12885