

JOHN R. LAMARSH
68 North Chatsworth Avenue
Larchmont, New York 10538
914/834-8576

Regulatory

File Cy.

April 8, 1976



Mr. Roger Boyd
Director
Division of Project Management
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Re: Docket Nos. 50-272, 50-311

Dear Mr. Boyd:

I note on page 5, paragraph 4, of NUREG-0050, Recommendations Related to Browns Ferry Fire, that "the fire detectors installed in the control room were of the ionization type which did not detect the products of combustion generated by the cable fire and did not alarm."

Could you tell me if it has been determined whether the detectors installed in the Salem Nuclear Generating Station, which I understand are also of the ionization type, are sensitive to the products of combustion of the cables used in that plant.

Sincerely yours,

John R. Lamarch
John R. Lamarch

JRL:bg
cc: Mayor David A. Fogg
Mr. Oliver F. Ayars
William C. Horner, Esq.



3638