

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

BWGS, LLC
1410 Hancel Parkway
Mooreville, IN 46155

REPORT NUMBER(S) 2019001 / 2019001

2. NRC/REGIONAL OFFICE

Region III
U. S. Nuclear Regulatory Commission
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-39102 / 030-39098

4. LICENSE NUMBER(S)

13-35481-01 / 13-35481-02E

5. DATE(S) OF INSPECTION

Feb. 4 - Mar. 1, 2019

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- ☐ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Deborah A. Piskura, Senior Health Physicist		3/1/19
BRANCH CHIEF	Aaron T. McCraw, Chief, MIB		3/1/19

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: BWGS, LLC 1410 Hancel Parkway Mooreville, IN 46155 REPORT NUMBER(S) 2019001 / 2019001		2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352	
3. DOCKET NUMBER(S) 030-39102 / 030-39098	4. LICENSE NUMBER(S) 13-35481-01 / 13-35481-02E	5. DATE(S) OF INSPECTION Feb. 4 - Mar. 1, 2019	
6. INSPECTION PROCEDURES USED 87128	7. INSPECTION FOCUS AREAS 03.01 - 03.07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03214 / 03251	2. PRIORITY 5	3. LICENSEE CONTACT Tony Bayt, Bus.Affairs & Compliance	4. TELEPHONE NUMBER (812) 325-3777
---	----------------------	--	---

☒ Main Office Inspection Next Inspection Date: March 1, 2024

☐ Field Office Inspection _____

☐ Temporary Job Site Inspection _____

PROGRAM SCOPE

This was an initial, announced inspection of a small company authorized to possess and distribute various models of exempt halide lamps containing krypton-85. The possession and E-distribution licenses were issued on June 8, 2018 and June 11, 2018 respectively. The licensee retained the services of a consulting RSO, Dr. James Schweitzer, of Purdue University. All licensed material was contained within the arc tube of the lamp. The licensee obtained these lamps from China and transferred the products to customers within the US. At the time of this inspection, the licensee possessed approximately 600 lamps. In 2018, the licensee reported that it distributed 496 lamps.

This inspection consisted of interviews with licensee personnel; observations of product security and storage; a review of select records including periodic distribution reports for 2018; and a tour of the warehouse storage areas.

This inspection included in office review through March 1, 2019, of product distribution information not available during the on-site inspection. This inspection included a discussion on the licensee's intent to divest its licensed material (transfer the lamps to a retail firm) and terminate the NRC licenses.

No violations of NRC requirements were identified during this inspection.