



ARKANSAS POWER & LIGHT COMPANY

POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

August 28, 1979

2-089-15

Mr. K. V. Seyfrit, Director
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Subject: Arkansas Nuclear One-Unit 2
Docket No. 50-368
License No. NPF-6
Reportable Occurrence Report
No. 50-368/79-059
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9, we have attached the subject report concerning a power supply failure for the Control Room Radiation Monitor causing isolation of the Control Room ventilation.

Very truly yours,

David C. Trimble

David C. Trimble
Manager, Licensing

DCT:REI:nak

Attachment

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Norman Haller, Director
Office of Management and
Program Analysis
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. W. D. Johnson
U.S. Nuclear Regulatory Commission
Post Office Box 2090
Russellville, Arkansas 72801

7909050465

915106