

CONTROL BLOCK:

							(1)
--	--	--	--	--	--	--	-----

0	1	N	C	B	E	P	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5			
7	8	LICENSEE CODE						14	LICENSE NUMBER										25	LICENSE TYPE					30	CAT				58

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	-	0	3	2	4	7	0	8	0	5	7	9	8	0	8	3	0	7	9	9
60	61									68	69					74	75							80
DOCKET NUMBER											EVENT DATE							REPORT DATE						

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While performing PT 4.1.1, Reactor Building Exhaust Vent Monitoring Check, the out-

0 3 | board supply damper would not stay closed, with the control switch in the "close"

0 4 | position.

05 | Technical Specifications 3.6.5.2, 6.9.1.9b

0	6
---	---

08

8 9

0 9

7 8

SYSTEM CODE

S C 11

9 10

CAUSE CODE

E 12

11

CAUSE SUBCODE

G 13

12

COMPONENT CODE

I N S T R U 14

13 18

COMP. SUBCODE

S 15

19

VALVE SUBCODE

Z 16

20

17	LER/RO REPORT NUMBER	EVENT YEAR			SEQUENCE REPORT NO.			OCCURRENCE CODE		REPORT TYPE			REVISION NO.				
		7	9	—	0	4	8	/	0	3	L	—	0				
		21	22	23	24	25	26	27	28	29	30	31	32				
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
E	18	Z	19	Z	20	Z	21	0	0	0	0	N	23	N	24	A	25
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The control switch on the RTGB was slightly out of adjustment. The switch was re-

1 1 | adjusted, tested, and returned to service. The automatic isolation on these dampers

1 2 | was always functional. This is considered an isolated event and no further action is

1 3 | required.

1	4	
---	---	--

8 9 FACILITY STATUS 30 METHOD OF DISCOVERY 32 DISCOVERY DESCRIPTION 80

1 5 E 28 0 8 0 29 NA B 31 Periodic Test 32

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z (33) Z (34) NA NA

7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	37	Z	38	NA	39

PERSONNEL INJURIES										
NUMBER			DESCRIPTION (41)							
1	8		0	0	0	40	NA			

7 8 9 11 12

916330 ~~916330~~

LOSS OF OR DAMAGE TO FACILITY						(43)
		TYPE		DESCRIPTION		
1	9	Z	(42)	NA		

PUBLICITY
ISSUED DESCRIPTION (45)
2 0 N (44) NA 7909 060 225 NRC USE ONLY

NAME OF PREPARED A. C. Tollison, Jr.

PHONE 919-457-9521