

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

August 29, 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

HARTSVILLE AND PHIPPS BEND NUCLEAR PLANTS - GENERAL ELECTRIC DESIGN
DEFICIENCY - SAFETY RELIEF VALVE CONTROL SYSTEM

Initial report of the subject reportable deficiency was made to
J. K. Rausch, NRC-OIE, Region II, on October 11, 1977. The first
and second interim reports were submitted on November 14, 1977, and
May 11, 1978, respectively. In compliance with paragraph 50.55(e)
of 10 CFR Part 50, we are enclosing the final report of the subject
deficiency. If you have any questions regarding this matter, please
get in touch with Tish Jenkins at FTS 854-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

917238

B019
5/11

7909060267