

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

August 29, 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

PHIPPS BEND NUCLEAR PLANT UNITS 1 AND 2 - REPORTABLE DEFICIENCY -
HIGH PRESSURE CORE SPRAY DIESEL GENERATOR SWITCHGEAR WIRING
DISCREPANCIES (NCR PBN-033)

Initial report of the subject deficiency was made to F. S. Cantrell, NRC-OIE, Region II, on August 2, 1979. In compliance with paragraph 50.55(e) of 10 CFR Part 50, we are enclosing the first interim report of the subject deficiency. It is anticipated that our final report will be transmitted to you on or before December 14, 1979. If you have any questions regarding this matter, please get in touch with Tish Jenkins at FTS 854-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

915259

7909060283

Bo19
S.11