

* CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	-	0	3	2	5	7	0	8	0	8	7	9	8	0	9	0	6	7	9	9
60	61	DOCKET NUMBER					68	69	EVENT DATE					74	REPORT DATE					80				

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2	While performing PT 1.1.13P, High Steamline Radiation Channel Alignment and Function
0	3	Test, Main Steam Line Hi Rad Monitor "B" was found to be actuating at 3.95 X background
0	4	while the allowable limit is \leq 3.5 X background.
0	5	Technical Specifications 2.2.1, 6.9.1.9a
0	6	
0	7	
0	8	

09		SYSTEM CODE M C		11	CAUSE CODE X		12	CAUSE SUBCODE Z		13	COMPONENT CODE I N S T R U						14	COMP. SUBCODE Y		15	VALVE SUBCODE Z		16
7	8	9	10		11		12		13						18		19				20		
17		LER/RO REPORT NUMBER		EVENT YEAR 7 9		21	22	SEQUENTIAL REPORT NO. 0 5 6		24	26	OCCURRENCE CODE 0 3		28	29	REPORT TYPE L		30	REVISION NO. 0		32		
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		22	ATTACHMENT SUBMITTED		23	NPRD-4 FORM SUB.		24	PRIME COMP. SUPPLIER		25	COMPONENT MANUFACTURER			
E	18	Z	19	Z	20	Z	21	0	0	0	0	N	23	Y	24	N	25	G	0	8	0		
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The out of tolerance reading was attributed to instrument drift. The monitor was re-

1 1 calibrated and returned to service. General Electric will be requested to provide

1 2 technical assistance in determining the cause of the instrument drift and determining

1 3 the corrective action. A supplement report will be issued when the required corrective

1 4 action has been determined.

7		8		9		FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		80			
1		5		E		28		0		9		5		29		NA		44	
7		8		9		10		12		13		45		46		80			
ACTIVITY		CONTENT		RELEASED		OF RELEASE		AMOUNT OF ACTIVITY		35		LOCATION OF RELEASE		36		80			
1		6		Z		33		Z		34		NA		44		45		80	
7		8		9		10		11		12		13		45		80			
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION		39		37		Z		38		NA		80	
1		7		0		0		0		37		Z		38		NA		80	
7		8		9		10		11		12		13		45		80			
PERSONNEL INJURIES		NUMBER		DESCRIPTION		41		40		NA		44		45		80			
1		8		0		0		0		40		NA		44		80			
7		8		9		10		11		12		13		45		80			
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION		43		42		NA		44		45		80			
1		9		Z		42		NA		44		45		46		80			
7		8		9		10		11		12		13		45		80			
PUBLCITY		ISSUED		DESCRIPTION		45		44		NA		44		45		80			
2		0		N		44		NA		44		45		46		80			
7		8		9		10		11		12		13		45		80			

NAME OF PREPARER A. C. Tollison, Jr.

PHONE: 919-457-9521