



UNIVERSITY OF MISSOURI

Research Reactor Facility

August 2, 1979

Research Park
Columbia, Missouri 65211
Telephone (314) 882-4211

United States Regulatory Commission
Office of Inspection & Enforcement
Region III
Glen Ellyn, IL 60137

Docket No. 50-186
Re: Inspection Report 050-186/79-03

Gentlemen:

Nine health physics standard operating procedures and a preface which have been added to the MURR 10 MW Standard Operating Procedures, Volume 5, Health Physics are enclosed for your inspection. These are submitted as compliance with Detail item 7 of the referenced inspection report. Assigned copies of the procedures will be maintained in key offices throughout the facility to provide access for all radiation workers. General distribution of unassigned copies will be made at Instructions to Workers meetings explaining the procedures.

Your comments are invited.

Sincerely,

Orval L. Olson, Manager
Reactor Health Physics

OLO/mb

Enclosures

cc: R. M. Brugger
D. M. Alger
C. McKibben


Don M. Alger
Associate Director
Research Reactor Facility

357002

7909170

477

AUG 6 1979



COLUMBIA

KANSAS CITY

ROLLA

ST. LOUIS

an equal opportunity institution