

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	D	C	C	N	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5			
7	8	9	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58	59

CON'T

0 1 7 8 REPORT SOURCE L 6 0 5 0 0 0 3 1 8 7 0 9 0 2 7 9 8 0 9 1 3 7 9 9 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | At 0043 while performing a surveillance test, control element assembly (CEA)

03 | 43 slipped to 100 inches. Reactor power was reduced to less than 70 percent

at 0140 in accordance with T.S. 3.1.3.1. CEA 43 was withdrawn and leveled

[b] (5) with its group at 0143. LER's 78-48 (U-1) and 79-24 (U-2) describe similar events.

0	6
---	---

08 7 8 9 POOR ORIGINAL

7 8 9 10 11 12 13 14 15 16

(17) LER NO REPORT NUMBER: 7 19 21 22
 EVENT YEAR: 7 19
 SEQUENTIAL REPORT NO.: 0 2 8 24 25 26
 OCCURRENCE CODE: 0 3 28 29
 REPORT TYPE: L 30
 NO: 0 32

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
Z	18	E	19	B	20	Z	21	0	0	0	0	N	23	N	24	N	25	P	3	1	4
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The slipped CEA is assumed to be the result of a voltage fluctuation in the 15

11 1-volt power supply. A design modification to improve the reliability of the

1 2 | system by installing dual power supplies (FCR 70-72) is to be installed during

13 the next refueling outage.

1	4	
---	---	--

FACILITY STATUS				% POWER			OTHER STATUS (30)		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION (32)	
1	5	E	(28)	1	0	0	(29)	NA	3	(31)	Surveillance Test	

ACTIVITY CONTENT		AMOUNT OF ACTIVITY (35)		LOCATION OF RELEASE (36)	
RELEASED	OF RELEASE	11A	11B	11A	11B
1	6	7	23	7	23

PERSONNEL EXPOSURES	
NUMBER	DESCRIPTION
33	NA
34	NA

1 7 0 0 0 37 2 38 NA

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	2	3	4	5	6
		Z	Z	Z	(40) NA

7 8 9 11 12 80
LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION
357045 790917050

7 8 9 10 90

PUBLICITY (45)

NARC USE ONLY

2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

NAME OF PREPARER S. M. Davis

PHONE: (301) 234-7942

*NRC USE ONLY