



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

September 14, 1979

D. L. ASWELL
Vice President-Power Production

LPL 11994
Q-3-A35.02.01
Q-3-A35.07

Mr. K. V. Seyfrit, Director, Region IV
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit #3
Interim Report of Significant Construction
Deficiency Number 13
Reactor Containment Building
Dome Concrete

Dear Mr. Seyfrit:

In accordance with the requirements of 10CFR50.55(e), we are submitting two (2) copies of the Interim Report for the subject Significant Construction Deficiency No. 13. Additionally as previously agreed to, you will be notified 48 hours prior to the resumption of placement of concrete in the containment building dome.

Yours very truly,

D. L. Aswell

DLA:TFG:smd

Enclosures

- cc: 1) Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
(with 15 copies of report)
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
(with one copy of report)

360083 BORG
S 11

7909180355