

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

012 367-7791

912-367-7781

NHC USE ONLY

967 009

Georgia Power Company
Plant E. I. Hatch
Baxley, Georgia 31513

Cause Description and Corrective Actions (continued)

of baseline data for the welds which were missed during preservice inspection. Section IWC-2100 of the ASME Section XI Code permits this substitution since construction surface examinations (visual inspection and penetrant tests) conform to ASME Section Code requirements, and the documentation packages are a part of the plant's permanent records. The preservice final report will reflect the data substitution.

967 010