

TIC

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

August 28, 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Serial No. 622
FO/FHT:baw
Docket No. 50-338
License No. NPF-4

3/11/81
CO: 622:03

Dear Mr. O'Reilly:

IE Bulletin 79-17
North Anna Power Station Unit 1

In response to the subject Bulletin, "Pipe Cracks in Stagnant Borated Water Systems at PWR Plants", we are performing the review requested to identify applicable piping systems. However, due to the volume of material that must be reviewed, we will not be able to meet your requested response date of August 25, 1979. We expect our review to be completed within the next two weeks and will provide the results by September 14, 1979.

Very truly yours,

W. C. Stallings
C. M. Stallings

Vice President-Power Supply
and Production Operations

cc: Director
Division of Operating Reactors

324
990321

7909240226

790600
OFFICIAL COPY