

ILLINOIS POWER COMPANY

U-0103
L08-79(08-20)-0

500 SOUTH 27TH STREET, DECATUR, ILLINOIS 62525

August 20, 1979

Mr. James G. Keppler
Director, Region III
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137


Dear Mr. Keppler:

- Reference: 1) IE Bulletin No. 79-03, "Logitudinal Weld Defects in ASME SA-312 Type 304 Stainless Steel Pipe Spools Manufactured by Youngstown Welding and Engineering Company"; March 12, 1979
- 2) Letter, G. E. Wuller (IPC) to J. G. Keppler (NRC); "Clinton Power Station Units 1 & 2;" May 10, 1979; U-0093, L08-79(05-10)-0

Clinton Power Station Units 1 & 2
Docket Nos. 50-461 and 50-462
Construction Permits No. CPPR-137 & CPPR-138

Reference 1 requested information concerning application of type ASME SA-312 welded (without filler metal) pipe manufactured by Youngstown Welding and Engineering Company. Reference 2 informed you that we would be able to respond to this request by December 31, 1979. We have completed our investigation and determined that no ASME SA-312 welded (without filler metal) pipe manufactured by Youngstown Welding and Engineering Company is or is intended to be installed in any safety-related systems at Clinton Power Station.

Sincerely,



G. E. Wuller
Supervisor - Licensing
Generation Engineering Department

PEW/jh

cc: NRC Office of Inspection & Enforcement
Division of Reactor Construction Inspection
Washington, DC 20555

AUG 24 1979

7009270 758

1042 078