

**POOR ORIGINAL**

August 17, 1979  
L-79-227

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:PJK  
50-250/79-11  
50-251/79-11  
(Supplemental Response)

19 AUG 23 AID: 48

USNRC REGION II  
ATLANTA, GEORGIA

As requested by Mr. P. J. Kellogg during an August 8, 1979 telephone call to members of my staff, Florida Power & Light Company (FPL) submits the following supplement to its July 12, 1979 response to the subject inspection report.

In response to Finding B.1 of the inspection report (Plant Work Orders accomplished without a procedure were not inspected or reviewed by the Quality Control Department), FPL committed to initiate a program of Quality Control Department review of Plant Work Orders accomplished without a procedure on nuclear safety related equipment. This program will include review by the Quality Control Department of such Plant Work Orders before the work is performed. This program will provide for inclusion of any required inspection points in the Plant Work Orders.

Very truly yours,

*Robert E. Uhrig*

Robert E. Uhrig  
Vice President  
Advanced Systems & Technology

REU/DWJ/MAS:pg

cc: Robert Lowenstein, Esquire

1030 330

7 909280 477

790623  
OFFICIAL COPY