



Carolina Power & Light Company

September 10, 1979

TIC
50-324
305

FILE: NC-3516(B)

SERIAL: GD-79-2248

SEP 12 8:48

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Washington, D. C. 20555

ATTENTION: Director, Division of Reactor
Construction Inspection

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NOS. 1 & 2
LICENSE NOS. DPR-71 AND DPR-62
DOCKET NOS. 50-325 AND 50-324
RESPONSE TO IE BULLETIN 79-15

Gentlemen:

In response to your letter of July 11, 1979, transmitting IE Bulletin 79-15 concerning deep draft pump deficiencies, Carolina Power & Light Company submits the following information:

Twelve items were addressed regarding deep draft pump deficiencies. An investigation has revealed that the Brunswick Steam Electric Plant does not use pumps of this type in safety-related applications, and, therefore, has no additional response to these items.

We trust that this information satisfies the request of IE Bulletin 79-15.

Yours very truly,

B. J. Furr
Manager
Generation Department

RMP:CSB:jmb*

cc: Mr. James P. O'Reilly

1087 135

7910030

216

790394

OFFICIAL COPY