

Unit 2

LICENSEE EVENT REPORT

Report No. 2-79-43/1T

CONTROL BLOCK: 

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1	P	A	P	B	S	2	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
8	9					14	15											25	26							57	CAT	58
LICENSEE CODE						LICENSE NUMBER												LICENSE TYPE										

NOT

REPORT SOURCE: 1 0 5 0 - 0 2 7 7 1 0 9 0 6 7 9 8 0 9 2 0 7 9 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2 The inspection program performed in response to IE Bulletin 79-02 identified two anchors in one support which had contact between the bolt shells and the support plate. These anchors are associated with the high pressure service water (HPSW) system line in the Unit 2 A RHR room.

3

4

5

6 Even though failure of the pipe during a seismic event would affect two HPSW containment cooling subsystems the safety significance is considered minimal because LPCI and redundant RHR subsystems are available.

7

8

SYSTEM CODE S H 9		CAUSE CODE B 12		CAUSE SUBCODE C 13		COMPONENT CODE S U P P O R T 14		COMP. SUBCODE A 15		VALVE SUBCODE Z 16	
LER/RO REPORT NUMBER 17		EVENT YEAR 7 9 21 22		SEQUENTIAL REPORT NO. 0 4 3 24 26		OCCURRENCE CODE 0 1 28 29		REPORT TYPE T 30		REVISION NO. 0 32	
ACTION TAKEN A 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22		ATTACHMENT SUBMITTED Y 23	
NPRD-4 FORM SUB. N 24		PRIME COMP. SUPPLIER A 25		COMPONENT MANUFACTURER I 26		27		28		29	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

0 | Contact between the bolt shells and support plate was caused by improper

1 | installation of the bolt anchor shells. The defective bolt shells have

2 | been removed and replaced by wedge type anchor bolts and have been suc-

3 | cessfully torque tested. The resulting anchor bolt safety factor attain-

4 | ed is greater than 5.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	E	0	9	8	N/A	D	Work in IE Bulletin 79-02		
ACTIVITY CONTENT		AMOUNT OF ACTIVITY		LOCATION OF RELEASE					
6	Z	Z	N/A	N/A					
PERSONNEL EXPOSURES		PERSONNEL INJURIES							
7	0	0	0	0	0	0	0	0	0
NUMBER		TYPE		DESCRIPTION		NUMBER		DESCRIPTION	
0		Z		N/A		0		N/A	
LOSS OF OR DAMAGE TO FACILITY		LOSS OF OR DAMAGE TO FACILITY							
1	Z	1	1	1	1	1	1	1	1
TYPE		DESCRIPTION		TYPE		DESCRIPTION			
Z		N/A		Z		N/A			

4 3 10  
 PUBLICITY  
 ISSUED DESCRIPTION (45)  
 2 0 N (44) N/A  
 4 3 10  
 NRC USE ONLY  
 68 69

NAME OF PREPARER

W. J. Cooney

PHONE: (215) 841-5020

NRC USE ONLY

10