

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

October 4, 1979

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:


MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-"&# License No. DPR-22

Leak in Reactor Vessel Peak Pressure Indicator

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.2.a in that protection and ECCS settings would have been less conservative than required. Redundant instruments were fully operable.

Yours very truly,



L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/jh

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
MPCA
Attn: J W Ferman

1138 306

-over-

7910100392