

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	D	C	C	N	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT		58

CON'T

REPORT SOURCE 7 8 0 1 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

DOCKET NUMBER 0 5 0 0 0 3 1 7 7 0 9 2 6 7 9 8 1 0 1 1 7 9 9

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | A hydraulic snubber (1-15-8 Table 3.7-4) was removed from operation to repair

23 attached support plate. The snubber support plate was repaired and the snubber

04 placed back in operation on 9/28/79. This is not a repetitive occurrence.

05 T.S. 3.7.8.1.

Q	F	
---	---	--

0	7
---	---

0	8	
---	---	--

7 8 9

SYSTEM CODE C J 11

CAUSE CODE B 12

CAUSE SUBCODE C 13

COMPONENT CODE S U P P O R T 14

COMP. SUBCODE B 15

VALVE SUBCODE Z 16

(17) LER/RO REPORT NUMBER EVENT YEAR REPORT NO. CODE TYPE NO.
 [7 | 9] [—] [0 | 5 | 1] [/] [0 | 3] [L] [—] [0]
 21 22 23 24 25 26 27 28 29 30 31 32

ACTION TAKEN [A] (18) [Z] (19) EFFECT ON PLANT [Z] (20) SHUTDOWN METHOD [Z] (21) HOURS [0] [0] [0] [0] (22) ATTACHMENT SUBMITTED [N] (23) NPD-4 FORM SUB. [N] (24) PRIME COMP. SUPPLIER [A] (25) COMPONENT MANUFACTURER [8] [1] [3] [0]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Anchors attaching snubber to wall were found deficient during testing I.A.W.

11 I&E Bulletin 79-02. Deficient anchors were replaced and the hanger restored

1	2
---	---

 to full operation with 72 hours.

1	3
---	---

1	4
---	---

FACILITY STATUS (28) 1 5 E
 % POWER 1 0 0 (29) NA
 OTHER STATUS (30)
 METHOD OF DISCOVERY (31) B
 DISCOVERY DESCRIPTION (32) Concrete Anchor Test Program

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 7 8 9 10 11 44 45 8

7 8 9 10 11 44 45 8

NA NA

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0					
2	8	9	10	11					
12	13	14	15	16					
17	18	19	20	21					
22	23	24	25	26					
27	28	29	30	31					
32	33	34	35	36					
37	38	39	40	41					
42	43	44	45	46					
47	48	49	50	51					
52	53	54	55	56					
57	58	59	60	61					
62	63	64	65	66					
67	68	69	70	71					
72	73	74	75	76					
77	78	79	80	81					
82	83	84	85	86					
87	88	89	90	91					
92	93	94	95	96					
97	98	99	100	101					

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	2	0	0	0	40 NA

1		9		Z		(42)		NA		7178 192	
LOSS OF OR DAMAGE TO FACILITY				(43)							
TYPE				DESCRIPTION							

7 8 9 10
PUBLICITY
ISSUED DESCRIPTION (45) 7910130 322 NRC USE ONLY

2	0	7	(44)	NA	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99
---	---	---	------	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

NAME OF PREPARER R. P. Heibel/T. L. Sydnor

PHONE: (301) 234-7942/7979