

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

716 Edney Building

October 15, 1979

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

POOR ORIGINAL

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-259 - FACILITY OPERATING LICENSE DTR-33 - REPORTABLE OCCURRENCE
REPORT BPRO-50-259/7923

The enclosed report provides details concerning daily source checks on
CAM's O-RR-90-252, 1-RR-90-250, 2-RR-90-250, and 3-RR-90-250 which were
missed due to airborne contamination on the refuel floor during normal
operation of units 1 and 2 and with unit 3 in a refueling outage. This
report is submitted in accordance with Browns Ferry unit 1 Technical
Specification 6.7.2.b(3).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. R. Calhoun
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)

Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)

Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

R. F. Sullivan, NRC Inspector, Browns Ferry

1176 195

A002
5/11

7910180 460