

CONTROL BLOCK:

						(1)
--	--	--	--	--	--	-----

01 M A P P S 1 2 0 0 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 1 4 5

7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31

REPORT SOURCE: 0 1 7 8
DOCKET NUMBER: 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
EVENT DATE: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20
REPORT DATE: 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

On October 2, 1979, while performing surveillance test 8.7.4.3, it was

03 | discovered that CV5065-26 took longer to close than the five (5) seconds

04 | allowed by Technical Specification Table 3.7.1.

0 9 7 8

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

S D 11 E 12 X 13 I N S T R U 14 S 15 Z 16

17	LER/RO REPORT NUMBER	EVENT YEAR			SEQUENTIAL REPORT NO.			OCCURRENCE CGOE		REPORT TYPE		REVISION NO.																						
		7	9	21	22	0	3	8	24	26	0	3	28	29	L	30	31	0	32															
	ACTION TAKEN	FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER																		
	E	18	Z	19	33	34	Z	20	35		21	36	22	37	0	0	0	0	40	N	23	41	N	24	42	A	25	43	M	3	0	2	26	44

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of this event was a lever arm on the switch being out of adjust-

11 ment. The valve was found to operate correctly. The switch was adjusted.

1 3

1 4

1 5 E 28 0 8 0 29 NA B 31 Routine Surveillance Test 32

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES			41		45		80	
NUMBER			TYPE		DESCRIPTION		(39)	
1	2	0 0 0	(37)	Z	(38)	NA		

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	NA

1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		13																																																																																															

7910190 451 NRC USE ONLY

NAME OF PREPARED G. G. Whitney

PHONE (617) 746-7900