



**METROPOLITAN EDISON COMPANY** SUBSIDIARY OF GENERAL PUBLIC UTILITIES CORPORATION

OFFICE BOX 480 MIDDLETOWN, PENNSYLVANIA 17057

TELEPHONE 717-844-4041

June 6, 1975

Mr. J. P. O'Reilly, Director  
Directorate of Regulatory Operations  
Region I  
631 Park Avenue  
King of Prussia, Pa. 19406

Operating License DPR-50  
Docket 50-289

Subject: Abnormal Occurrence No. AO 75-16

Dear Mr. O'Reilly:

This telegram is to confirm the telecon between Lee Spessard (Region I-DRO), and J. J. Colitz (THI Unit I Superintendent) at 1630 hours, June 6, 1975.

Violation of Technical Specification 2.3.1 in that the variable low reactor coolant system pressure trip setpoints for three RPS channels were found to be less conservative than the setpoint listed in Table 2.3.1 (Page 2-9) of the Technical Specifications.

The required and actual trip points for the channels out of specification were as follows:

<u>Channel</u>	<u>Table 2.3-1 Trip Setpoint at 590° F. (16.25 T out - 7756)</u>	<u>Actual Trip Point Measured at the Bistable</u>
A	1831.5	1827.4
B	1831.5	1828.9
D	1831.5	1827.5

The variable low reactor coolant system pressure trip setpoints were being checked as part of routine Surveillance Procedure 1303-4.1, "Reactor Protection System Surveillance". All other reactor protection system trip setpoints were tested and found to be within Technical Specification limits.

The out-of-specification channels have been recalibrated and retested, and the resulting trip setpoints were verified as being within Technical Specification limits.

Very truly yours,

*J. G. Herbein*  
J. G. Herbein  
Station Superintendent  
THI Nuclear Station

1476 166

JGH:amt

7910240

903