

IT OFFICE BOX 400 MIDDLETOWN, PENNSYLVANIA 17057

TELEPHONE 717-641-4041

August 23, 1975

Mr. J.P. O'Reilly
Director of Regulatory Operations
Region 1
625 Park Avenue
King of Prussia, Pa. 19406

POOR ORIGINAL

Operating License DPR-50
Docket 50-289

Subject: Abnormal Occurrence No. AO 75-28

Dear Mr. O'Reilly:

This telegram is to confirm the conversation between Lee Spassard (Region I-NRC) and J.J. Colitz (TMI Unit 1 Superintendent) at 1400 hours on 23 July 1975.

The following report is submitted in accordance with paragraph 1.3.d (page 1-6) of the Technical Specifications.

On August 20, 1975 the Turbine Driven Emergency Feed Pump was run for Surveillance Testing. The pump operated successfully on steam supplied from A Steam Generator through MS V13A. When an attempt was made to test the pump on steam supplied from the B Steam Generator, the associated valve, MS V13B, opened in response to pressing the open pushbutton but closed when the open pushbutton was released.

Investigation revealed a failed pressure switch. The failed pressure switch would have prevented the valve opening on an automatic start signal.

The pressure switch was replaced and the Turbine Driven Feed Pump was successfully tested on steam supplied from the B Steam Generator within the 40 minute allowable time period.

Very truly,
J.J. Colitz

J.J. Colitz
Unit 1 Superintendent

JJC/...

1476 177

8910240 906