



METROPOLITAN EDISON COMPANY SUBSIDIARY OF GENERAL PUBLIC UTILITIES CORPORATION

POST OFFICE BOX 480 MIDDLETOWN, PENNSYLVANIA 17057

TELEPHONE 717-244-4041

October 10, 1975

Mr. J. P. O'Reilly, Director
Directorate of Regulatory
Region I
631 Park Avenue
King of Prussia, Pa., 19405

POOR ORIGINAL

Operating License DPR-50
Docket 50-289

Subject: Abnormal Occurrence No. AO 75-35

Dear Mr. O'Reilly:

This telegram is to confirm the conversation between Mr. Lee Spessard (Region I-NRC) and Mr. J.J. Colitz (EMI-Unit 1 Superintendent) at 1600 hours on October 10, 1975.

The following report is submitted in accordance with paragraph 6.7.2.a.1 (page 6-11) of the Technical Specifications.

On October 10, 1975, the boric acid mix tank was designated as the tank to meet Tech. Spec. 3.2.2 requirements. When an attempt was made to transfer boric acid from the boric acid mix tank to a reclaimed boric acid tank, it was found that flow could not be established.

Immediate investigation revealed an obstruction in the tank outlet line. The line was cleared and the flow path from the boric acid mix tank to the boric acid mix tank pumps was verified, thus restoring the tank to operable status.

The heat trace on the associated lines was checked and the temperature was found to be satisfactory.

A reclaimed boric acid tank will be designated as the tank to meet the requirements of Tech Spec. 3.2.2 and the cause for the obstruction will be investigated.

Very truly yours,

J. J. Colitz

J. J. Colitz
Unit 1 Superintendent

JJC/lca

1476 243

7910240 934