



METROPOLITAN EDISON COMPANY SUBSIDIARY OF GENERAL PUBLIC UTILITIES CORPORATION

POST OFFICE BOX 480 MIDDLETOWN, PENNSYLVANIA 17057

TELEPHONE 717-944-4041

April 22, 1975

Mr. J.P. O'Reilly, Director
Directorate of Regulatory Operations
Region I
631 Park Avenue
King of Prussia, Pa. 19406

POOR ORIGINAL

Operating License DPR-50
Docket 50-289

Subject: Abnormal Occurrence No AO 75-12

Dear Mr. O'Reilly:

This telegram is to confirm the telecon between Lee Spessard Region I-NRC, and J.G. Herbein (TMI Station Superintendent) at 1400 hours 21 April 1975.

The following report is submitted in accordance with paragraph 6.7.2.a.1 (page 6-11) of technical specifications.

On 21 April, while performing High and Low Pressure Injection Surveillance Testing, RR-P1B (Reactor Building Emergency Cooling River Pump) failed to start on signal. The pump was then manually started from the control room using the control switch.

The redundant pump, RR-P1A, was tested to verify operability.

An investigation is currently in progress to determine the reason RR-P1B failed to start on receipt of test signal.

Following the determination of the reason RR-P1B failed to start, the necessary corrective action will be taken and RR-P1B will be tested and returned to service.

Very truly yours,

J.G. Herbein

J.G. Herbein
Station Superintendent

1476 253

JGH/dmm

4682

7910240936