



METROPOLITAN EDISON COMPANY SUBSIDIARY OF GENERAL PUBLIC UTILITIES CORPORATION

POST OFFICE BOX 480 MIDDLETOWN, PENNSYLVANIA 17057 TELEPHONE 717-944-4041

June 25, 1975

Mr. J. P. O'Reilly, Director  
Directorate of Regulatory Operations  
Region 1  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

POOR ORIGINAL

Operating License DPR-50  
Docket 50-289

Subject: Abnormal Occurrence No. A0-75-21

Dear Mr. O'Reilly:

This telegram is to confirm the telecon between Bert Davis (Region 1-DRO) and J. J. Colitz (TMI Unit 1 Superintendent) at 1700 hours, June 25, 1975.

Violation of Technical Specification 2.3.1 in that the high reactor coolant temperature trip bistable for Reactor Protection System Channel C failed to trip during routine RPS Surveillance Testing. Table 2.3-1 (Page 2-9) of the Technical Specification requires that the bistable trip at a maximum temperature of 619°F.

The bistable failed to trip because a component failure in the signal converter prevented the trip signal from reaching the bistable.

The high temperature trip feature for the remaining three RPS channels was immediately checked and the bistables were found to trip within Technical Specification limits.

The defective signal converter is currently under repair. Upon completion of repairs, the high temperature trip feature will be completely tested prior to returning RPS Channel C to service.

Very truly yours,

*J. J. Colitz*  
J. J. Colitz  
Unit 1 Superintendent  
TMI Nuclear Station

JJC:VPO:hh

1476 277  
7910240 748