



METROPOLITAN EDISON COMPANY SUBSIDIARY OF GENERAL PUBLIC UTILITIES CORPORATION

POST OFFICE BOX 480 MIDDLETOWN, PENNSYLVANIA 17057

TELEPHONE 717-944-4041

June 19, 1975

Mr. J.P. O'Reilly, Director
Directorate of Regulatory Operations
Region I
631 Park Avenue
King of Prussia, Pa. 19406

POOR ORIGINAL

Operating License DPR-50
Docket 50-289

Subject: Abnormal Occurrence No. AO 75-19

Dear Mr. O'Reilly:

This telegram is to confirm the telecon between Lee Spessard (Region I-DRO), and J.J. Colitz (TMI Unit I Superintendent) at 1700 hours, June 19, 1975.

Violation of Technical Specification 2.3.1 in that the variable low reactor coolant system pressure trip setpoint for one RPS channel was found to be less conservative than the setpoint listed in Table 2.3.1 (Page 2-9) of the Technical Specifications.

The required and actual trip point for the channel out of specification was as follows:

<u>Channel</u>	<u>Table 2.3-1 Trip Setpoint at 590° F. (16.25 T out - 7756)</u>	<u>Actual Trip Point Measured at the Bistable</u>
C	1831.5	1831.2

The variable low reactor coolant system pressure trip setpoints for all four RPS channels were being tested to determine instrument drift as specified in Abnormal Occurrence Report Number AO 50-289/75-16. The setpoints for channels A, B and D were found to be within Technical Specification limits.

The out-of-specification channel has been recalibrated and retested, and the resulting trip setpoint was verified as being within Technical Specification limits.

Very truly yours,

J.J. Colitz for J.G. Herbein
J.G. Herbein
Station Superintendent
TMI Nuclear Station

JGH/db

1476 290

7910240 954