

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME: 01 P A T M I Z Z 14 15 00 -00 00 00 -00 25 26 7 / / / / / / 30 31 0 / / / 32

CON'T: 01 7 8 9 CATEGORY: 57 58 REPORT TYPE: Z 59 REPORT SOURCE: L 60 DOCKET NUMBER: 0 5 0 -0 2 8 9 61 68 EVENT DATE: 0 4 / 5 / 7 7 69 74 REPORT DATE: 0 7 / 2 9 / 7 7 75 80

EVENT DESCRIPTION

02 7 8 9 During the refueling outage while updating of the valves nameplate
03 7 8 9 data, the vendor-certified valve capacity was found to be less than
04 7 8 9 that required in the safety analysis. The analysis was recom-
05 7 8 9 mended and a Tech. Spec. change will be submitted to correctly state
06 7 8 9 the relief capacity.

SYSTEM CODE: 07 7 8 9 10 Z Z CAUSE CODE: 11 A COMPONENT CODE: 12 Z Z Z Z Z Z 17 PRIME COMPONENT SUPPLIER: 43 Z COMPONENT MANUFACTURER: 44 Z 9 9 9 47 VIOLATION: 48 N

CAUSE DESCRIPTION

08 7 8 9 A total combined relief valve capacity value of 623,400 lb/hr from a
09 7 8 9 vendor valve drawing was used in making the assumption that
10 7 8 9 619,300 lb/hr would be a suitable value to use in the safety analysis.

FACILITY STATUS: 11 7 8 9 A % POWER: 10 0 0 12 13 OTHER STATUS: 44 N A METHOD OF DISCOVERY: 45 A DISCOVERY DESCRIPTION: 46 N A
FORM OF ACTIVITY RELEASED: 12 Z 9 CONTENT OF RELEASE: 10 0 11 AMOUNT OF ACTIVITY: 44 N A LOCATION OF RELEASE: 45 N A

PERSONNEL EXPOSURES

13 7 8 9 11 0 0 12 Z 13 N A

PERSONNEL INJURIES

14 7 8 9 11 0 0 12 N A

OFFSITE CONSEQUENCES

15 7 8 9 N A

LOSS OR DAMAGE TO FACILITY

16 7 8 9 10 Z N A

PUBLICITY

17 7 8 9 Included in regular weekly news release

ADDITIONAL FACTORS

18 7 8 9

19 7 8 9

NAME: W E Patis PHONE: 929-3601 (ext. 8-114)

POOR ORIGINAL

1476 340

7910250546