

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M D C C N 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0 1 L 0 5 0 0 0 3 1 8 7 1 0 2 4 7 9 8 1 1 0 7 7 9 9
8 9 REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During a reanalysis of the #12 and 21 Diesel Generator pipe supports
0 3 as required by IE Bulletin 79-14, it was discovered that the air
0 4 start system hangers did not meet seismic requirements. To meet T.S.
0 5 3.8.1.1 started D/G's within one hour and ran them continuously, thereby
0 6 removing reliance upon diesel air start system. A similar occurrence
0 7 was reported in LER 79-34 (U-2).

0 8
0 9
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
E E 11 B 12 A 13 S U P I O R T 14 A 15 Z 16
17 LER/RO REPORT NUMBER 7 9 0 3 9 0 1 0 1 T 0
21 22 23 24 26 27 28 29 30 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
F 18 F 19 Z 20 Z 21 0 0 0 0 N 23 N 24 A 25 X 9 9 9 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The portion of the diesel air start system which had previously been
1 1 thought to have seismic supports has been reanalyzed and the existing
1 2 supports upgraded and new supports added. This is the only item of non-
1 3 compliance that was identified by the required IE Bulletin 79-14
1 4 Walkdowns.

1 5 FACILITY STATUS 28 0 0 0 29 N/A 30 METHOD OF DISCOVERY 31 Visual Inspection 32
1 6 ACTIVITY RELEASED OF RELEASE 33 Z 34 Z N/A 35 AMOUNT OF ACTIVITY 36 LOCATION OF RELEASE 37
1 7 PERSONNEL EXPOSURES 38 0 0 0 39 Z 40 N/A 41
1 8 PERSONNEL INJURIES 42 0 0 0 43 N/A 44
1 9 LOSS OF OR DAMAGE TO FACILITY 45 Z 46 N/A 47
2 0 PUBLICITY 48 Z 49 N/A 50
ISSUED DESCRIPTION 51 Z 52 N/A 53
NAME OF PREPARER R. P. Heibel PHONE (301) 234-7943
7911130 255
1320 066
NRC USE ONLY