



NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

November 7, 1979

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

RCIC Temperature Switch Setpoint Drift

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.2.a in that a protection instrument setting was found to be less conservative than required. Redundant instruments were fully operable.

Yours very truly,

David M. Mayer for

L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/jh

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
MPCA
Attn: J W Ferman

1323 157

-over-

7911130 322

S