

## LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 M N C C N 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5  
 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0 1 REPORT SOURCE L 6 0 5 10 10 10 13 1 8 7 1 1 1 1 2 7 9 8 1 1 1 0 6 7 9 9  
 80 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While investigating #21 diesel generator voltage regulation  
 0 3 problems, it was necessary to take #21 diesel generator out of  
 0 4 service from 1240 to 1435, October 12, 1979, to repair the voltage  
 0 5 regulator. The operability of the remaining A.C. sources was demon-  
 0 6 strated as required by T.S. 3.8.1.1. This is not a repetitive  
 0 7 occurrence.

0 8 80

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE  
 E E 11 E 12 A 13 I N S T R U 14 X 15 7 16  
 9 10 11 12 13 18 19 20  
 17 LER RO REPORT NUMBER 17 9 21 22 23 24 25 26 27 28 29 30 31 32  
 33 ACTION TAKEN 34 FUTURE ACTION 35 EFFECT ON PLANT 36 SHUTDOWN METHOD 37 HOURS 38 ATTACHMENT SUBMITTED 39 NPD-4 FORM SUB. 40 PRIME COMP. SUPPLIER 41 COMPONENT MANUFACTURER  
 C 18 Z 19 Z 20 Z 21 0 0 0 0 0 22 N 23 Y 24 A 25 8 0 9 3 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The Basler voltage regulator board #32101-102 showed signs of having an  
 1 1 overheated resistor (R-25) in its voltage feedback circuit, the cause of  
 1 2 the overheating could not be determined. The voltage regulator board  
 1 3 was replaced in its entirety. This is not a generic problem and no  
 1 4 further action is planned.

1 5 80

1 6 FACILITY STATUS POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (37)  
 E 28 1 0 0 29 N/A A 31 Operator Observation

1 7 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)  
 Z 33 E 34 N/A N/A

1 8 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)  
 0 0 0 37 Z 38 N/A

1 9 PERSONNEL INJURIES NUMBER DESCRIPTION (41)  
 0 0 0 40 N/A

2 0 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)  
 Z 42 N/A

2 1 PUBLICITY ISSUED DESCRIPTION (45)  
 Z 44 N/A

7911140 279

NRC USE ONLY

NAME OF PREPARER R. P. Heibel/E. R. Bauer

PHONE (301)234-7943/7955