

CONTROL BLOCK: 

1	2	3	4	5	6
---	---	---	---	---	---

 (1)

9 N | C | E | E | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 57 CAT 58  
 LICENSEE CODE 14 LICENSE NUMBER 25 LICENSE TYPE 30

CON'T

REPORT SOURCE L 6 0 5 0 - 0 3 2 5 7 1 0 1 5 7 9 8 1 1 0 7 7 9 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During normal operation, the operator noticed that the "Core Spray/RHR Pump Running"

03 | annunciator would not reset following a periodic test on the RHR pumps.

04 | Technical Specifications 3.3.3, 6.9.1.9b

0	5	
---	---	--

0	6
---	---

07

0	8	
---	---	--

0 9 7 8 S F 11 D 12 A 13 I N S T R U 14 E 15 Z 16 9 10 11 12 13 14 15 16 17 18 19 20

(17)	LER/RO REPORT NUMBER	EVENT YEAR			REPORT NO.			CODE		TYPE			NO.									
		7	9	—	0	8	5	/	0	3	L	—	0									
		21	22	23	24	25	26	27	28	29	30	31	32									
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPF-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER						
A	(18)	Z	(19)	Z	(20)	Z	(21)	0	0	0	(22)	N	(23)	Y	(24)	N	(25)	B	0	6	9	(26)
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Condensate in the conduit had accumulated in the switch causing a sticking of the re-

set spring cylinder. The switch was replaced, calibrated and returned to service.

1 The conduit was refitted with a new end fitting for a tighter end seal. This is

1 considered an isolated event

FACILITY STATUS (28) E (28) % POWER 0 9 9 (29) NA OTHER STATUS (30) METHOD OF DISCOVERY (31) A (31) DISCOVERY DESCRIPTION (32) Operator Surveillance

ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z	(38) NA	(39)		

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	NA

		LOSS OF OR DAMAGE TO FACILITY		(43)
		TYPE	DESCRIPTION	
1	9	Z(42)	NA	069

PUBLICITY  
 ISSUED DESCRIPTION (45)  
 2 0 N (44) NA 7911140 345 NRC USE ONLY

NAME OF PREPARER A. C. Tollison, Jr.

PHONE: 919-457-9521

NRC USE ONLY

7911140 345

0  
0  
0  
0  
0  
0  
0