

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	C	0	F	S	V	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	2	0	4		5				
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36				
LICENSEE CODE										LICENSE NUMBER										LICENSE TYPE										CAT		58	

CON'T

0	1	L	6	0	5	0	0	0	2	6	7	7	1	0	1	8	7	9	8	1	1	0	9	7	9	9					
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36		
REPORT SOURCE		DOCKET NUMBER										EVENT DATE										REPORT DATE									

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 On two occasions during the period of October 18 and 19, 1979, with reactor at power.

0 3 motor driven fire pump was removed from service to repair a leaking air release valve.

0 4 These periods of time constitute operation in a degraded mode of LCO 4.2.6 and are re-

0 5 portable per Technical Specification AC 7.5.2(b)2. No affect on health or safety of

0 6 the public. No accompanying occurrence or probable consequences.

0 7

0 8

0	9	A	B	11	E	12	B	13	V	A	L	V	E	X	14	F	15	C	20	7	9	21	0	5	0	22	0	3	23	L	30	0	32	X	9	9	9	26		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE										COMP. SUBCODE		VALVE SUBCODE		EVENT YEAR		SEQUENTIA- REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.												
LER RO REPORT NUMBER		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER																						

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The motor driven fire pump was removed from service in order to repair a water leak on

1 1 a McCracken air vacuum release valve. The valve was removed from service and disas-

1 2 sembled. Damaged float was replaced and bent float arm repaired and adjusted. Valve

1 3 and pump were returned to service.

1 4

1	5	C	28	0	0	8	29	N/A	0	31	Personnel Observation	0	32	Discovery Description	N/A	36	Location of Release
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION									

1	6	Z	33	Z	34	N/A	35	Amount of Activity	N/A	36	Location of Release
7	8	9	10	11	12	13	14	15	16	17	18
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION					

1	7	0	0	0	37	Z	38	N/A	39	Description
7	8	9	10	11	12	13	14	15	16	17
PERSONNEL INJURIES		NUMBER		DESCRIPTION						

1	8	0	0	0	40	N/A	41	Description
7	8	9	10	11	12	13	14	15
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION				

1	9	Z	42	N/A	43	Description
7	8	9	10	11	12	13
PUBICITY		ISSUED		DESCRIPTION		

NAME OF PREPARER

J. W. Gahm

PHONE:

(303) 785-2253

NRC USE ONLY

1354 343

7911190417