



NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

November 15, 1979

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-282 License No. DPR-42

Faulty Seismic Installation of Cooling
Water System Modification in Unit 1 Containment

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.2(c) since it represents inadequate implementation of administrative controls.

Yours very truly,

A handwritten signature in cursive script that reads "L O Mayer".

L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/ak

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
MPCA
Attn: J W Ferman

1355 055

-over-

7911190 436