

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	D	C	C	N	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	56

CON'T

REPORT SOURCE L 6 0 5 0 C 0 3 1 8 7 1 0 2 7 7 9 8 1 1 1 5 7 9 9

60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

ROCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | At 0250 while filling the refueling pool from the refueling water tank
03 | using #22 high pressure safety injection (HPSI) pump a mechanic reported
04 | that the pump was smoking. Subsequent investigation revealed that the
05 | in board pump seal had failed. The pump was placed out of service and
06 | #21 HPSI pump was aligned for the boration flow path per T.S. 3.1.2.1.
07 | No core alterations or positive reactivity additions were in progress.
08 | This is not a repetitive event.

SYSTEM CODE S F 11		CAUSE CODE E 12		CAUSE SUBCODE B 13		COMPONENT CODE P U M P X X 14				COMP. SUBCODE B 15		VALVE SUBCODE Z 16	
LER/RO REPORT NUMBER 7 9 8		EVENT YEAR 7 9 21 22		SEQUENTIAL REPORT NO. 0 4 1 23 24 25 26		OCCURRENCE CODE / 27		REPORT TYPE L 28 29 30		REVISION NO. 0 31 32			
ACTION TAKEN X 18		FUTURE ACTION X 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22 37 40		ATTACHMENT SUBMITTED N 23 41		NPRD-4 FORM SUB. Y 24 42	
PRIME COMP. SUPPLIER N 25 43		COMPONENT MANUFACTURER B 2 6 5 26 44 47											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Mechanical seal and pump internals to be inspected and repairs initiated

1 1 as soon as practicable. Cause and future corrective actions to be

1 2 determined and included in update report.

1 3

1 4

FACILITY STATUS (28) H 1 5 7 8 9
 % POWER 0 0 0 (29) 10 12 13 N/A 44
 OTHER STATUS (30)
 METHOD OF DISCOVERY (31) A 45 46 Maintenance worker observation 80
 DISCOVERY DESCRIPTION (32)
 ACTIVITY CONTENT (35) 1 6 7 8 9 Z 33 10 11 Z 34 N/A 44
 RELEASED OF RELEASE
 AMOUNT OF ACTIVITY
 LOCATION OF RELEASE (36) 45 46 N/A

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
000	(37) Z	(38) N/A

1355 130

PERSONNEL INJURIES	NUMBER	DESCRIPTION
1	1	N/A
2	1	N/A
3	1	N/A
4	1	N/A
5	1	N/A
6	1	N/A
7	1	N/A
8	1	N/A
9	1	N/A
10	1	N/A
11	1	N/A
12	1	N/A
13	1	N/A
14	1	N/A
15	1	N/A
16	1	N/A
17	1	N/A
18	1	N/A
19	1	N/A
20	1	N/A
21	1	N/A
22	1	N/A
23	1	N/A
24	1	N/A
25	1	N/A
26	1	N/A
27	1	N/A
28	1	N/A
29	1	N/A
30	1	N/A
31	1	N/A
32	1	N/A
33	1	N/A
34	1	N/A
35	1	N/A
36	1	N/A
37	1	N/A
38	1	N/A
39	1	N/A
40	1	N/A
41	1	N/A
42	1	N/A
43	1	N/A
44	1	N/A
45	1	N/A
46	1	N/A
47	1	N/A
48	1	N/A
49	1	N/A
50	1	N/A
51	1	N/A
52	1	N/A
53	1	N/A
54	1	N/A
55	1	N/A
56	1	N/A
57	1	N/A
58	1	N/A
59	1	N/A
60	1	N/A
61	1	N/A
62	1	N/A
63	1	N/A
64	1	N/A
65	1	N/A
66	1	N/A
67	1	N/A
68	1	N/A
69	1	N/A
70	1	N/A
71	1	N/A
72	1	N/A
73	1	N/A
74	1	N/A
75	1	N/A
76	1	N/A
77	1	N/A
78	1	N/A
79	1	N/A
80	1	N/A
81	1	N/A
82	1	N/A
83	1	N/A
84	1	N/A
85	1	N/A
86	1	N/A
87	1	N/A
88	1	N/A
89	1	N/A
90	1	N/A
91	1	N/A
92	1	N/A
93	1	N/A
94	1	N/A
95	1	N/A
96	1	N/A
97	1	N/A
98	1	N/A
99	1	N/A
100	1	N/A

POOR ORIGINAL

[illegible]

1 9 42 N/A

PUBLICITY
 ISSUED DESCRIPTION (45) 7911190 511 NRC USE ONLY
 2 0 7 8 9 10 68 69

NAME OF PREPARER S. M. Davis/D. Huseby

PHONE: (301) 234-7942/7997

NRC USE ONLY