

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

SYSTEM CODE 0 9		CAUSE CODE A A (11)		CAUSE SUBCODE C (13)		COMPONENT CODE I N S T R U (14)				COMP. SUBCODE P (15)		VALVE SUBCODE Z (16)	
EVENT YEAR 7 9		SEQUENTIAL REPORT NO. 0 9 4		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0		ACTION TAKEN B (18)		FUTURE ACTION H (19)	
EFFECT ON PLANT Z (20)		SHUTDOWN METHOD Z (21)		HOURS 0 0 0 0 (22)		ATTACHMENT SUBMITTED Y (23)		NPRD-4 FORM SUB. Y (24)		PRIME COMP. SUPPLIER A (25)		COMPONENT MANUFACTURER X 9 9 9 (26)	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

FACILITY STATUS (1) 5 (2) E (3) 0 (4) 9 (5) 1 (6) 29 (7) N/A (8) METHOD OF DISCOVERY (9) B (10) Periodic Test (11) DISCOVERY DESCRIPTION (12)
 % POWER (13) 0 (14) 9 (15) 1 (16) 29 (17) N/A (18) OTHER STATUS (19) 30 (20) METHOD OF DISCOVERY (21) B (22) Periodic Test (23) DISCOVERY DESCRIPTION (24)
 ACTIVITY CONTENT (25) 1 (26) 6 (27) Z (28) 33 (29) Z (30) 34 (31) N/A (32) AMOUNT OF ACTIVITY (33) 35 (34) LOCATION OF RELEASE (35) 36 (36)
 PERSONNEL EXPOSURES (37) 1 (38) 7 (39) 0 (40) 0 (41) 0 (42) Z (43) 38 (44) N/A (45) DESCRIPTION (46) 39 (47)
 PERSONNEL INJURIES (48) 1 (49) 4 (50) 0 (51) 0 (52) 0 (53) 40 (54) N/A (55) DESCRIPTION (56) 41 (57)
 LOSS OF OR DAMAGE TO FACILITY (58) 1 (59) 9 (60) Z (61) 42 (62) N/A (63) DESCRIPTION (64) 43 (65)
 PUBLICITY (66) 2 (67) 0 (68) N (69) 44 (70) 45 (71) 7911260 23/ (72) NRC USE ONLY (73)
 ISSUED (74) 2 (75) 0 (76) N (77) 44 (78) 45 (79) 7911260 23/ (80) N/A (81) (82) (83) (84) (85) (86) (87) (88) (89) (90)

POOR ORIGINAL

1401 254 ~~330~~

7911260 23/

NRC USE ONLY

NAME OF PREPARER A. C. Tollison, Jr.

PHONE: 919-457-9521

LER CONTINUATION -- RO# 2-79-94

Facility: BSEP Unit No. 2

Event Date: 10-25-79

the "Jumper & Wire Removal Procedure." An investigation is in progress at this time to ensure that all other annunciator wires are terminated correctly.

1401 255

3531